

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402295959

Date Received:
01/28/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10539
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP
Address: 1125 ESCALANTE DR
City: RANGELY State: CO Zip: 81648
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

| Contact Name | Phone | Email |
|------------------------|---------------------|------------------------------------|
| <u>Kellerby, Shaun</u> | <u>970-712-1248</u> | <u>shaun.kellerby@state.co.us</u> |
| <u>Utah Gas Corp</u> | <u>720-425-0303</u> | <u>inspections@utahgascorp.com</u> |

COGCC INSPECTION SUMMARY:

FIR Document Number: 679703772
Inspection Date: 04/17/2019 FIR Submit Date: 04/18/2019 FIR Status: _____

Inspected Operator Information:

Company Name: UTAH GAS OP LTD DBA UTAH GAS CORP Company Number: 10539
Address: 1125 ESCALANTE DR
City: RANGELY State: CO Zip: 81648

LOCATION - Location ID: 316020

Location Name: DRAGON TRAIL UNIT-62S102W Number: 21SWNW County: RIO BLANCO
Qtrqtr: SWN Sec: 21 Twp: 2S Range: 102W Meridian: 6
Latitude: 39.861507 Longitude: -108.856856

FACILITY - API Number: 05-103- -00 Facility ID: 231931

Facility Name: DRAGON TRAIL UNIT Number: 1150
Qtrqtr: SWN Sec: 21 Twp: 2S Range: 102W Meridian: 6
Latitude: 39.861507 Longitude: -108.856856

CORRECTIVE ACTIONS:

1 CA# 124393

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1). Date: 03/08/2019

Response: CA COMPLETED Date of Completion: 05/07/2019

Operator Comment: Secondary containment repaired

COGCC Decision: _____

COGCC
Representative:

2 CA# 124394

Corrective Action: Comply with Rule 603.f .

Date: 04/30/2019

Response: CA COMPLETED

Date of Completion: 05/07/2019

Operator
Comment: Debris removed

COGCC Decision: _____

COGCC
Representative:

3 CA# 124395

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 05/20/2019

Response: CA COMPLETED

Date of Completion: 05/07/2019

Operator
Comment: Stormwater BMP repaired and soil scour repaired

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions were completed 5/7/19 and follow up inspection on 5/17/19 indicated CA's resolved

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Robert Bleil

Signed:

Title: Regulatory Manager

Date: 1/28/2020 9:52:22 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number Description

| | |
|-----------|---|
| 402295965 | Photo of liner repaired |
| 402296006 | Follow up inspection #679704113 identifying CA's resolved |

Total Attach: 2 Files