

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402298512

Date Received:  
01/29/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Victoria Dizghinjili</u>	<u>303-825-4822</u>	<u>vdizghinjili@kpk.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 687400737  
Inspection Date: 01/07/2020 FIR Submit Date: 01/07/2020 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC Company Number: 46290  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 319877

Location Name: BEISEL UNIT-61S68W Number: 1SWNE County: \_\_\_\_\_  
Qtrqr: SWNE Sec: 1 Twp: 1S Range: 68W Meridian: 6  
Latitude: 39.996678 Longitude: -104.946144

FACILITY - API Number: 05-001- -00 Facility ID: 319877

Facility Name: BEISEL UNIT-61S68W Number: 1SWNE  
Qtrqr: SWNE Sec: 1 Twp: 1S Range: 68W Meridian: 6  
Latitude: 39.996678 Longitude: -104.946144

CORRECTIVE ACTIONS:

1 CA# 135739

Corrective Action: Location is within a designated setback location, bullplug or cap all loadlines per Rule 604.c.(2)O.

Date: 01/13/2020

Response: CA COMPLETED Date of Completion: 01/13/2020

Operator Comment: Bullplug on loadout valve has been installed. Please see attached pictures.

COGCC Decision: \_\_\_\_\_

Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.
--------------------	---

Date: 02/07/2020

Date of Completion: 01/22/2020

Operator Comment:	All berms at location have been repaired. Stained soil next to berm near load out line has been removed. Please see attached pictures.
-------------------	--

COGCC Decision:

## OPERATOR COMMENT AND SUBMITTAL

--

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed:

Date: 1/29/2020 3:59:50 PM

## ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402298550	Berms PIC2
402298560	Well PIC1
402298566	Completed CA PIC3

Total Attach: 3 Files