

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402302078

Date Received:

02/03/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Luke Kelly

720-315-8934

LKelly@Bonanzacrk.com

Brian Dodek

720-440-6100

BDodek@Bonanzacrk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697501028

Inspection Date: 01/10/2020

FIR Submit Date: 01/15/2020

FIR Status: _____

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Company Number: 8960

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 462951

Location Name: LATHAM

Number: 11-13 CPF

County: _____

Qtrqtr: NWN
W

Sec: 13

Twp: 4N

Range: 63W

Meridian: 6

Latitude: 40.317090

Longitude: -104.394190

FACILITY - API Number: 05-123- -00

Facility ID: 462951

Facility Name: LATHAM

Number: 11-13 CPF

Qtrqtr: NWN
W

Sec: 13

Twp: 4N

Range: 63W

Meridian: 6

Latitude: 40.317090

Longitude: -104.394190

CORRECTIVE ACTIONS:

1 CA# 135987

Corrective Action:

Date: 01/10/2020

Best management practices to stabilize and prevent weed establishment shall be implemented. Control, manage, and prevent weedy, annual vegetation on all topsoil stockpiles. If reseeding is an option for long-term protection and stabilization of topsoil, then the next favorable seeding opportunity shall be conducted.

The corrective date is not intended to be the date for which the Operator shall complete the corrective actions but rather the corrective date is the date the location was observed out of compliance, as it should be in compliance at all times.

Response: CA COMPLETED

Date of Completion: 01/13/2020

Operator Comment: The topsoil stockpile was mowed to remove and prevent the growth of the weedy vegetation. Following weed mitigation, the stockpile was seeded and resprayed with hydromulch to help stabilize and prevent windblown erosion.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 135988

Corrective Action: Comply with Rule 1002.f.(2) to install BMPs in accordance with good engineering practices, including a stabilized outlet.

Date: 01/10/2020

The corrective date is not intended to be the date for which the Operator shall complete the corrective actions but rather the corrective date is the date the location was observed out of compliance, as it should be in compliance at all times.

Response: CA COMPLETED

Date of Completion: 01/13/2020

Operator Comment: To comply with Rule 1002.f.(2), four stabilized sediment traps were installed to function as stormwater outlet structures

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Luke Kelly

Signed: _____

Title: Senior Env. Specialist

Date: 2/3/2020 5:32:40 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

| | |
|-----------|------------------|
| 402302102 | Latham CA Photos |
|-----------|------------------|

Total Attach: 1 Files