

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402304583

Date Received:
02/05/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10071
Name of Operator: HIGHPOINT OPERATING CORPORATION
Address: 555 17TH ST STE 3700
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>James. Brian</u>		<u>dnr_cogccengineering@state.co.us</u> <u>bjames@hpres.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 697500924
Inspection Date: 12/17/2019 FIR Submit Date: 12/18/2019 FIR Status: _____

Inspected Operator Information:

Company Name: HIGHPOINT OPERATING CORPORATION Company Number: 10071
Address: 555 17TH ST STE 3700
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 318581

Location Name: STATE-62N63W Number: 36SESE County: _____
Qtrqtr: SESE Sec: 36 Twp: 2N Range: 63W Meridian: 6
Latitude: 40.091190 Longitude: -104.378657

FACILITY - API Number: 05-123-00 Facility ID: 318581

Facility Name: STATE-62N63W Number: 36SESE
Qtrqtr: SESE Sec: 36 Twp: 2N Range: 63W Meridian: 6
Latitude: 40.091190 Longitude: -104.378657

CORRECTIVE ACTIONS:

1 CA# 135452

Corrective Action: Comply with Rule 1004.a. to remove (regardless of ownership) all debris, abandoned gathering line risers, and flowline risers, and equipment within three months of plugging (01/12/2018) the associated facility. All work should have been conducted by 3/12/2018.

Date: 03/12/2018

Collaborate with the landowner to determine mitigating measures that will allow reclamation work to be conducted in such a manner as to not interfere with agricultural activities or crop production.

Response: CA COMPLETED

Date of Completion: 02/05/2020

Operator Comment: DCP Equipment has been removed.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

2  CA# 135453

Corrective Action: Comply with Rule 1004.a. to remove all gravel, re-contour and re-grade the access road.

Date: 03/12/2018

Collaborate with the landowner to determine mitigating measures that will allow reclamation work to be conducted in such a manner as to not interfere with agricultural activities or crop production.

Response: CA COMPLETED

Date of Completion: 02/10/2020

Operator Comment: gravel will be removed, re-contour and re-grading of the access road will be done on 2/10/20.

COGCC Decision: **Not Approved**

COGCC Representative: COGCC Staff appreciates the update but is unable to approve this resolution as "Corrective Action Complete" because this is only documenting planned work. The Field Inspection Report Resolution Form was intended to alert the Inspector when corrective actions have been completed. Operator can respond separately to each corrective action once each corrective action has been completed.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Brian James

Signed: _____

Title: Land Manager

Date: 2/5/2020 3:19:15 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402304583	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files