

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



E*
re-

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL OTHER **Dry Hole**

2. NAME OF OPERATOR **Conrad Grenfell**

3. ADDRESS OF OPERATOR **632 W. El Camino, Sacramento, Calif.**

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface **Sec. 14 T6N R86W**

5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME **B. L. Morris**

9. WELL NO. **10**

10. FIELD AND POOL, OR WILDCAT **Curtis Anticline WC**

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA **NE SE Sec. 14 T6N R86W**

12. COUNTY OR PARISH **Routt** 13. STATE **Colo.**

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)

DEC 20 1965
OIL & GAS
CONSERVATION COM.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Moved casing rig in.
2. Run 10 sack plug in bottom of hole.
3. Pulled 2000' of 5 1/2" casing.
4. Run 10 sack plug at bottom of surface casing.
5. Run 10 sack plug at surface.
6. Regulation marker below plow dept.
7. Heavy mud was run between plugs.

NO PRIOR APPROVAL

BYE	
WRS	
JHM	
JAM	
FJP	
JJD	
FILE	

18. I hereby certify that the foregoing is true and correct

SIGNED W. J. Pippy Jr.

TITLE _____

DATE 18 Dec 65

(This space for Federal or State office use)

APPROVED BY W. J. Rogers

TITLE Director

DATE DEC 29 1965

VIOLATION
REMARKS:

*See Instructions on Reverse Side