

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402092188

Date Received:
07/01/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

6 of 6 CAs from the FIR responded to on this Form

6 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10110
Name of Operator: GREAT WESTERN OPERATING COMPANY LLC
Address: 1001 17TH STREET #2000
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Paluch, Kelly</u>	<u>970-364-2812</u>	<u>cogccinspections@gwogco.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 688402006
Inspection Date: 04/24/2019 FIR Submit Date: 04/24/2019 FIR Status: _____

Inspected Operator Information:

Company Name: GREAT WESTERN OPERATING COMPANY LLC Company Number: 10110
Address: 1001 17TH STREET #2000
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 320309

Location Name: EHLER-61S68W Number: 11SWSE County: ADAMS
Qtrqr: SWSE Sec: 11 Twp: 1S Range: 68W Meridian: 6
Latitude: 39.973703 Longitude: -104.965775

FACILITY - API Number: 05-001-00 Facility ID: 203427

Facility Name: EHLER Number: 34-11-1
Qtrqr: SWSE Sec: 11 Twp: 1S Range: 68W Meridian: 6
Latitude: 39.973703 Longitude: -104.965775

CORRECTIVE ACTIONS:

1 CA# 124569

Corrective Action: Location is within a floodplain, containment berms around the tanks must be made of steel or another engineer equivalent per Rule 603.h.(2)C. Refer to the 603.h guidance document for further details.

Date: 05/24/2019

Response: CA COMPLETED Date of Completion: 07/01/2019

Operator Comment: After discussion with inspector the battery has been deemed NOT in a floodplain.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 CA# 124570

Corrective Action: Anchor equipment ensuring anchors are engineered so the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 603.h.(2)B. Refer to the 603.h guidance document for further details.

Date: 05/24/2019

Response: CA COMPLETED

Date of Completion: 07/01/2019

Operator Comment: After discussion with inspector the battery has been deemed NOT in a floodplain.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 CA# 124571

Corrective Action: Anchor equipment ensuring anchors are engineered so the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 603.h.(2)B. Refer to the 603.h guidance document for further details.

Date: 05/24/2019

Response: CA COMPLETED

Date of Completion: 07/01/2019

Operator Comment: After discussion with inspector the battery has been deemed NOT in a floodplain.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

4 CA# 124572

Corrective Action: Install sign to comply with Rule 210.e.

Date: 05/24/2019

Response: CA COMPLETED

Date of Completion: 07/01/2019

Operator Comment: Signage was installed

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

5 CA# 124573

Corrective Action: Install proper guy line markers per Rule 1003.a

Date: 05/15/2019

Response: CA COMPLETED

Date of Completion: 07/01/2019

Operator Comment: Anchore removed from location

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

6 CA# 124574

Corrective Action: Comply with rule 603 f

Date: 05/08/2019

Response: CA COMPLETED

Date of Completion: 07/01/2019

Operator
Comment: all trash removed from location

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kelly Paluch

Signed: _____

Title: Sr. Admin Asst.

Date: 7/1/2019 9:29:39 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402092188	FIR RESOLUTION SUBMITTED
402092194	ANCHOR REMOVED
402092200	WELLHEAD SIGNAGE
402092204	TRASH REMOVED

Total Attach: 4 Files