

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402051895

Date Received:  
05/22/2019

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Beebe, Sabre

sabre.beebe@bpx.com

SanJuanCOGCC@bp.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 693900197

Inspection Date: 04/09/2019

FIR Submit Date: 04/18/2019

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

### LOCATION - Location ID: 325074

Location Name: SOUTHERN UTE 32-8-N32N8W Number: 1NWNE County: LA PLATA

Qtrqr: NWNE Sec: 1 Twp: 32N Range: 8W Meridian: N

Latitude: 37.049976 Longitude: -107.664599

### FACILITY - API Number: 05-067-00 Facility ID: 257024

Facility Name: SOUTHERN UTE 32-8; Number: 1-7

Qtrqr: NWNE Sec: 1 Twp: 32N Range: 8W Meridian: N

Latitude: 37.049976 Longitude: -107.664599

### CORRECTIVE ACTIONS:

1 ☒ CA# 124386

Corrective Action: Control weeds at the appropriate time, but before flowerset in 2019, and no later than June 1, 2019.

Date: 06/01/2019

Response: CA COMPLETED

Date of Completion: 05/08/2019

Operator Comment: Noxious weeds manually removed from location due to new seeding performed in the areas not utilized for current operations.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 124387

Corrective Action: Stormwater controls need to be installed to stabilize erosion within the project area. Stormwater controls need to be selected, sized, and installed using good engineering practices. Successful revegetation of areas not needed for production will help stabilize the project area.

Date: 05/18/2019

Response: CA COMPLETED

Date of Completion: 05/08/2019

Operator Comment: Seeding of areas around plugged well on same pad has been performed for stabilization. All possible areas that could be, were disc, seeded, mulched and crimped to establish vegetation for infiltration and slowing of stormwater flow. Well pad has plugged well Southern Ute 32-8 1-1 as well as on going production activity so amount of work that could be performed to enable on going production has been performed.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective Actions Complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 5/22/2019 7:43:36 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402051895	FIR RESOLUTION SUBMITTED
402051904	Compliance follow up form

Total Attach: 2 Files