

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402078222

Date Received:

06/18/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Beebe, Sabre SanJuanCOGCC@bp.com

Beebe, Sabre sabre.beebe@bpx.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900337

Inspection Date: 05/17/2019

FIR Submit Date: 05/22/2019

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 306851

Location Name: KENNEDY GU A-M34N8W Number: 21NWNW County: LA PLATA

Qtrqr: NWN Sec: 21 Twp: 34N Range: 8W Meridian: M
W

Latitude: 37.180803 Longitude: -107.727693

FACILITY - API Number: 05-067- -00 Facility ID: 269664

Facility Name: KENNEDY A Number: 2

Qtrqr: NWN Sec: 21 Twp: 34N Range: 8W Meridian: M
W

Latitude: 37.180803 Longitude: -107.727693

CORRECTIVE ACTIONS:

1 ☒ CA# 125424

Corrective Action: Control weeds. Due to the extent of the infestation here and surrounding oil and gas locations multiple control methods and applications will be needed.

Date: 06/09/2019

Revegetation and stabilization measures need to be installed in portions of the interim reclamation area that are poorly revegetating, such as the eastern fill slope and the cut-slopes (northern and western). Revegetation and stabilization activities need to be completed no later than June 30, 2019.

Response: CA COMPLETED

Date of Completion: 06/07/2019

Operator Comment: Noxious weeds treated within the lease area with herbicide. see attached

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 ☒ CA# 125425

Corrective Action: Stormwater controls along the access road need maintenance. Stabilization measures for erosion controls are needed along the well pad cut-slopes until long term stabilization is achieved.

Date: 06/30/2019

Response: CA COMPLETED

Date of Completion: 06/07/2019

Operator Comment: Seeding and hydromulching performed along cut areas of the lease in an attempt to re-establish vegetation via vegetation see attached.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions completed see attached

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 6/18/2019 7:15:36 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402078222	FIR RESOLUTION SUBMITTED
402078225	completion photos

Total Attach: 2 Files