

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402079714

Date Received:

06/18/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Beebe, Sabre

sabre.beebe@bpx.com

SanJuanCOGCC@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900228

Inspection Date: 04/17/2019

FIR Submit Date: 04/29/2019

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 333980

Location Name: KLUSMAN RANCES GAS UNIT-N33N8W Number: 11NWNE County: LA PLATA

Qtrqtr: NWNE Sec: 11 Twp: 33N Range: 8W Meridian: N

Latitude: 37.122774 Longitude: -107.682909

FACILITY - API Number: 05-067-00 Facility ID: 268611

Facility Name: KLUSMAN RANCHES Number: 2

Qtrqtr: NWNE Sec: 11 Twp: 33N Range: 8W Meridian: N

Latitude: 37.122774 Longitude: -107.682909

CORRECTIVE ACTIONS:

1 ☒ CA# 124659

Corrective Action: This is the second corrective action for stormwater erosion within the project area. Stormwater controls need to be installed to stabilize erosion within the project area. These need to be selected and installed using good engineering practices such as those described by CDOT in their erosion control and stormwater quality guides.

Date: 05/31/2019

Response: CA COMPLETED

Date of Completion: 06/05/2019

Storm water BMP's have been upgraded to handle potential stormwater flows. Rock rundowns have silt basins throughout to slow down water due to slope and prevent silt travel. Berm repaired to direct water flows to the

Operator Comment: rundowns and the existing BMP's have been cleaned out where needed. see attached.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective action addressed. See attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 6/18/2019 3:52:18 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402079714	FIR RESOLUTION SUBMITTED
402079718	CA completion form

Total Attach: 2 Files