

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/14/2020

Submitted Date:

02/14/2020

Document Number:

689901799

FIELD INSPECTION FORM

Loc ID 333716 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1801 BROADWAY SUITE 350
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 3 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266005	WELL	PR	06/16/2003	GW	071-07803	SANTA FE 43-27	RI
276208	WELL	PR	04/15/2005	GW	071-08303	SANTA FE 43-27 TR	RI

General Comment:

[This is a stormwater inspection.](#)
[See attached photos and additional details within this report.](#)

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is erosion issues along the main access road. Stormwater from the road is causing erosion along the side of the road. Stormwater directed from culvert outlets has caused erosion to occur. Areas of erosion need to be repaired, stabilized, and reclaimed. BMP's must be implemented in accordance with good engineering practice and must be maintained.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 03/14/2020

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Due to snow cover, other erosion issues may have not been noticed and not all nearby locations were inspected.	CostaR	02/14/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402314179	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5068943
689901800	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5068939