



STATE OF  
COLORADO

Allison - DNR, Rick <rick.allison@state.co.us>

---

## Babb #15-14

---

**Mark E. Brown** <mark@markusproduction.com>  
To: "Allison - DNR, Rick" <rick.allison@state.co.us>  
Cc: "Chesson, Robert" <Robert.Chesson@state.co.us>

Thu, Feb 6, 2020 at 8:47 AM

Rick,

I made some updates as you noted below and have "submitted" the Form 27.

Thx

Mark

**From:** Allison - DNR, Rick <rick.allison@state.co.us>  
**Sent:** Thursday, February 6, 2020 8:16 AM  
**To:** Mark E. Brown <mark@markusproduction.com>  
**Cc:** Chesson, Robert <Robert.Chesson@state.co.us>  
**Subject:** Re: Babb #15-14

Mark

On page 1, check Rule 905 pit closure.

For the soil sampling, analyze the center point at 10, or the material that appears impacted if you encounter impacted material at a shallower depth. Analyze the sample for TPH-GRO,DRO and ec,pH and SAR.

For the sidewall samples, analyze those samples in the upper 18" for ec,pH and SAR. If you encounter impacted material deeper then analyze that sample for TPH-GRO,DRO.

Let me know if you have questions,

Rick

Richard Allison, P.G.  
Environmental Protection Specialist, Northeast Colorado



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

P 970.461.2970 | C 970.623.0850

1120 Lincoln Street, Suite 801, Denver, CO 80203

[rick.allison@state.co.us](mailto:rick.allison@state.co.us) | [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)

On Wed, Feb 5, 2020 at 5:44 PM Mark E. Brown <[mark@markusproduction.com](mailto:mark@markusproduction.com)> wrote:

Rick,

Can you take a look at this Form 27 and see if you agree with our approach for this old produced water pit investigation prior to me submitting it in eForms?

Thanks

Mark

---

**From:** Mark E. Brown <[mark@markusproduction.com](mailto:mark@markusproduction.com)>  
**Sent:** Wednesday, February 5, 2020 4:08 PM  
**To:** 'Allison - DNR, Rick' <[rick.allison@state.co.us](mailto:rick.allison@state.co.us)>; 'Jeff Schneider' <[jeff@rivalservices.net](mailto:jeff@rivalservices.net)>  
**Cc:** 'Chesson, Robert' <[Robert.Chesson@state.co.us](mailto:Robert.Chesson@state.co.us)>  
**Subject:** RE: Babb #15-14

Rick,

Jeff was able to get a roustabout crew out to the Babb site last week and got all of the surface items taken care of. He took some pics of the area after clean up and I'll get those submitted with a FIFR report.

As for the Form 27, can you give me some guidance as to the approach you'd like to see here? My plan would be to take a core sample from the center of that pit site and then one from each of the 4 quadrant points as best identified as the "berms" to the pit area and have analyzed against the 910 table. Does that sound good to you? I may pull in a consultant to help me get this all done, but wanted a quick read from you first.

Thanks

Mark

Mark E. Brown

**MARKUS PRODUCTION, INC.**

39 Fairway Lane

Columbine Valley, CO 80123

720-350-8858

**From:** Allison - DNR, Rick <[rick.allison@state.co.us](mailto:rick.allison@state.co.us)>

**Sent:** Tuesday, January 28, 2020 8:15 AM

**To:** Jeff Schneider <[jeff@rivalservices.net](mailto:jeff@rivalservices.net)>

**Cc:** Mark Brown <[Mark@markusproduction.com](mailto:Mark@markusproduction.com)>; Chesson, Robert <[Robert.Chesson@state.co.us](mailto:Robert.Chesson@state.co.us)>

**Subject:** Re: Babb #15-14

Hi Jeff

Thank you for the update. Please get the Form 27 submitted as soon as possible with plan for us to review prior to your collecting samples so we agree on the approach. Call Bob Chesson or me if you have any questions or problems with the Form 27.

Rick

Richard Allison, P.G.  
Environmental Protection Specialist, Northeast Colorado



P 970.461.2970 | C 970.623.0850

1120 Lincoln Street, Suite 801, Denver, CO 80203

[rick.allison@state.co.us](mailto:rick.allison@state.co.us) | [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)

On Thu, Jan 23, 2020 at 5:08 PM Jeff Schneider <[jeff@rivalservices.net](mailto:jeff@rivalservices.net)> wrote:

Rick,

I left you a voice mail but thought I would follow up with an email so you had my contact Info. I am working for Markus Production to get the inspection corrective actions for the Babb 15-14 taken care of (Doc# 693700349). I actually tried to get a crew lined up in August but couldn't find one available until October and then we had a couple snow storms in October and November. I didn't want to dig all over in the pasture in the snow to try to find the oil stained dirt and debris. I have a crew lined up to be out there no later than next Wednesday to get started on getting the oil stained dirt and all the debris cleaned and will work with Mark on getting the Form 27 turned in and get the required samples. I will send pictures as soon as we get the surface issues taken care of.

Please let me know if you have any questions.

Thanks

Jeff

970-381-9588

Thanks,

Jeff Schneider

President  
Rival Services, LLC  
Fort Morgan, CO 80701  
970-867-9437  
<http://www.rivalservices.net/>

