

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402323515

Date Received:
02/25/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

BAKER DAVID

dbaker@auroramp.com

FITZGERALD EDIE

ediefitzgerald@tcenergylc.com

Mack, Ronald

ronaldmack@tcenergylc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901717

Inspection Date: 01/30/2020

FIR Submit Date: 01/31/2020

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 308662

Location Name: NEW ELK-633S68W Number: 26NWSW County: LAS ANIMAS

Qtrqr: NWS Sec: 26 Twp: 33S Range: 68W Meridian: 6
W

Latitude: 37.138440 Longitude: -104.971820

FACILITY - API Number: 05-071- -00 Facility ID: 278250

Facility Name: NEW ELK Number: 26-12

Qtrqr: NWS Sec: 26 Twp: 33S Range: 68W Meridian: 6
W

Latitude: 37.138440 Longitude: -104.971820

CORRECTIVE ACTIONS:

1 CA# 136248

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 02/28/2020

Response: CA COMPLETED

Date of Completion: 02/05/2020

Operator Comment: The deteriorated muffler on the liquid ring compressor was replaced and all valves, pipes and fittings were securely fastened to maintain good mechanical condition.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 136249

Corrective Action: Implement or modify BMPs for improved material handling and spill prevention.
Immediately clean up area.
5 days to implement improved procedures.

Date: 02/05/2020

Response: CA COMPLETED

Date of Completion: 02/05/2020

Operator Comment: The oily waste was removed from the PC engine skid and the liquid ring compressor skid immediately. Non-structural BMP's were implemented for improved material handling. The field employees attended a training regarding improved material handling techniques.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 2/25/2020 3:54:16 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files