

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402127071

Date Received:

07/31/2019

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 77330

Name of Operator: SG INTERESTS I LTD

Address: 100 WAUGH DR SUITE 400

City: HOUSTON State: TX Zip: 77007

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

inspection@sginterests.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900449

Inspection Date: 06/18/2019

FIR Submit Date: 07/05/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: SG INTERESTS I LTD

Company Number: 77330

Address: 100 WAUGH DR SUITE 400

City: HOUSTON State: TX Zip: 77007

LOCATION - Location ID: 429333

Location Name: Federal 12-89-7 Number: 1 County: GUNNISON

Qtrqtr: NESE Sec: 7 Twp: 12S Range: 89W Meridian: 6

Latitude: 39.025470 Longitude: -107.371390

FACILITY - API Number: 05-051- -00 Facility ID: 429334

Facility Name: Federal 12-89-7 Number: 1

Qtrqtr: NESE Sec: 7 Twp: 12S Range: 89W Meridian: 6

Latitude: 39.025470 Longitude: -107.371390

CORRECTIVE ACTIONS:

1 ☒ CA# 126762

Corrective Action: Stormwater and erosion controls need to be installed to stabilize erosion within the project area.  
Cracking in berms needs to be monitored and stabilization measures employed if cracks deepen or slipping occurs.  
Stormwater controls need to be installed using good engineering practices such as those described in CDOT manuals for stormwater and erosion control.

Date: 07/19/2019

Response: CA COMPLETED

Date of Completion: 07/18/2019

The northwestern project area has been stabilized with additional erosion control measures. Monitoring of the cracking in the berm continues, however the cracks have been fixed. Due to this effort, more seeding is required. The cutslope and this berm area are scheduled for seeding and hydromulch.

Operator  
Comment:

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amanda Blanchard

Signed: \_\_\_\_\_

Title: Env & Reg Manager

Date: 7/31/2019 11:53:50 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

402127071	FIR RESOLUTION SUBMITTED
402127085	CA Photos

Total Attach: 2 Files