

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Unmarked wellhead		
Corrective Action:	. Unmarked tank and unmarked wellhead, Corrective Action Install sign to comply with Rule 210.b.Corrective Action Date 4/6/2020.	Date:	04/06/2020
Type	BATTERY		
Comment:	Adiquate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adiquate		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text" value="Adiquate"/>		Date: _____
Corrective Action:	<input style="width: 100%;" type="text"/>		
Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris (dead weeds) on and around the location.		
Corrective Action:	Location is within a designated setback location, remove trash or debris per Rule 604.c. (2)P. Corrective Action Date. 3/24/2020	Date:	03/24/2020
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Bradenhead	# 1		corrective date
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Leak at wellhead.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule #605.d. Corrective action Date 24hrs 3/4/2020.	Date:	03/04/2020
Type: Horizontal Heated Separator	# 1		
Comment:			

Corrective Action:	Date:
--------------------	-------

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		39.965351,-104.565588

Comment: Bull plug missing from loadoff line.

Corrective Action: Location is within a designated setback location, bullplug or cap all loadlines per Rule #604.c.(2)O. Corrective action Date 3/10/2020.	Date: 03/10/2020
--	------------------

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:

Corrective Action:	Date:
--------------------	-------

Venting:

Yes/No	NO	Date:	
Comment:			
Corrective Action:			Date:

Flaring:

Type		Date:	
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 202813 Type: WELL API Number: 001-08218 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday, March 3, 2020 at approximately 9:39am, I, Inspector Chane Finkenbinder, Conducted an on-site inspection at (UPRR – BESSIE #1) (Painted Pegasus Petroleum LLC), at (Location # 320144 or API #001-08218) in (Adams County) Colorado. While there, I observed (Shut in Well) During this inspection the following possible compliance issues were observed:</p> <p>Debris (dead weeds) on and around the location. Location is within a designated setback location, remove trash or debris per Rule 604.c.(2)P. Corrective Action Date. 3/24/2020. See attached photo #3.</p> <p>Unmarked wellhead. Unmarked tank and unmarked wellhead, Corrective Action Install sign to comply with Rule 210.b. Corrective Action Date 4/6/2020. See attached photo #4.</p> <p>Bull plug missing from loadoff line. Location is within a designated setback location, bullplug or cap all loadlines per Rule #604.c.(2)O. Corrective action Date 3/10/2020. See attached photo #2.</p> <p>Leak at wellhead. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule #605.d. Corrective action Date 24hrs 3/4/2020 See attached photo #5.</p> <p>I spoke with (Troy Mouet) with (Painted Pegasus Petroleum LLC) what was discussed. That there was a leak on the wellhead and that someone is on the way out there to get it taken care of.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	finkenbc	03/03/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700900047	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5084566