

# Inspection Photos

3/6/2020

Operator: WINDSOR ENERGY GROUP LLC -  
10081

Location ID: 315696  
Rio Blanco County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC - 10081

Location ID: 315696



**Photo 1:** Photo taken from the access road, facing west. Photo shows access road remains evident; Unable to find evidence that additional reclamation has been conducted in accordance with Rule 1004.a, and per corrective actions.



**Photo 2:** See comments under photo 1.



## Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC - 10081

Location ID: 315696



**Photo 3:** Photo taken from the northern access road. Photo shows trash debris.



**Photo 4:** Photo shows access road has not been recontoured or regraded



## Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC - 10081

Location ID: 315696



**Photo 5:** Photo shows erosion degradation on access road.



**Photo 6:** Photo shows trash debris.



Inspection Photos  
Operator Name: WINDSOR ENERGY GROUP LLC - 10081  
Location ID: 315696



**Photo 7:** Continued from photo 6.



**Photo 8:** Photo taken from the Location, facing southeast.  
Photo shows metal poles remaining on Location.



## Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC - 10081

Location ID: 315696



**Photo 9:** Photo taken from the well site, facing west. Photos 9-10 provide an overview of the well site.



**Photo 10:** Continued from photo 9.



## Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC - 10081

Location ID: 315696



**Photo 11:** Photo taken from the access road, facing east.  
Photo shows trash debris.



**Photo 12:** See comments under photo 1.



Inspection Photos  
Operator Name: WINDSOR ENERGY GROUP LLC - 10081  
Location ID: 315696



**Photo 13:** Photo shows trash debris.



**Photo 14:** Photo shows trash debris.