

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402218277

Date Received:
10/23/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46685
Name of Operator: KINDER MORGAN CO2 CO LP
Address: 1001 LOUISIANA ST SUITE 1000
City: HOUSTON State: TX Zip: 77002

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Michael Hannigan</u>	<u>970-882-5532</u>	<u>michael_hannigan@kindermorgan.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900904
Inspection Date: 10/03/2019 FIR Submit Date: 10/09/2019 FIR Status: _____

Inspected Operator Information:

Company Name: KINDER MORGAN CO2 CO LP Company Number: 46685
Address: 1001 LOUISIANA ST SUITE 1000
City: HOUSTON State: TX Zip: 77002

LOCATION - Location ID: 436555

Location Name: CB Number: 3 County: MONTEZUMA
Qtrqr: LOT 7 Sec: 11 Twp: 38N Range: 19W Meridian: N
Latitude: 37.568930 Longitude: -108.911790

FACILITY - API Number: 05-083-00 Facility ID: 436564

Facility Name: CB Number: 3
Qtrqr: LOT 7 Sec: 11 Twp: 38N Range: 19W Meridian: N
Latitude: 37.568930 Longitude: -108.911790

CORRECTIVE ACTIONS:

1 CA# 131546

Corrective Action: Stormwater controls need to be installed to stabilize erosion within the project area. Date: 10/25/2019

Response: CA COMPLETED Date of Completion: 10/17/2019

Operator Comment: At the time of the inspection, storm water from the well pad was accumulating in a flat portion of the interim reclamation area located east of the pad. The cultivation pattern east of the pad provided channels for the storm water to travel south where the ground surface changes from flat to a positive grade which concentrated runoff and caused some soil erosion. A Kinder Morgan contractor was mobilized to re-grade the CB-3 well location and modify the surface drainage of the graveled well pad on October 17, 2019. The re-graded well pad now directs runoff away from the east and south toward the County Road borrow ditches located north and west of the location. See attached response and photos.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Hannigan

Signed: _____

Title: EHS Supervisor

Date: 10/23/2019 1:59:12 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402218277	FIR RESOLUTION SUBMITTED
402219064	CA #131546 Response & Photos

Total Attach: 2 Files