

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402239870

Date Received:  
12/03/2019

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 44390

Name of Operator: JAVERNICK OIL

Address: 3040 E MAIN

City: CANON CITY State: CO Zip: 81212

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Javernick, James

719-275-3040/719-671-3787

javernick1@gmail.com

Costa, Ryan

ryan.costa@state.co.us

Kosola, Jason

jason.kosola@state.co.us

**COGCC INSPECTION SUMMARY:**

FIR Document Number: 693900050

Inspection Date: 02/28/2019

FIR Submit Date: 03/12/2019

FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: JAVERNICK OIL

Company Number: 44390

Address: 3040 E MAIN

City: CANON CITY State: CO Zip: 81212

**LOCATION - Location ID: 322265**

Location Name: ROB HIAWATHA-620S69W Number: 8SENE County: FREMONT

Qtrqtr: SENE Sec: 8 Twp: 20S Range: 69W Meridian: 6

Latitude: 38.326360 Longitude: -105.124250

**FACILITY - API Number: 05-043- -00 Facility ID: 210087**

Facility Name: ROB HIAWATHA Number: 2

Qtrqtr: SENE Sec: 8 Twp: 20S Range: 69W Meridian: 6

Latitude: 38.326360 Longitude: -105.124250

**CORRECTIVE ACTIONS:**

1 ☒ CA# 123148

Corrective Action: Stabilization measures and stormwater controls need to be installed to stabilize the bank of the erosional channel, and manage stormwater erosion within the project area. This needs to be an engineered long-term solution sufficient to stabilize the cut-bank, and address run-on and runoff issues with properly sized and installed stormwater and erosion controls.

Date: 04/12/2019

Response: CA COMPLETED

Date of Completion: 04/22/2019

Operator Comment: Stabilization measures and stormwater controls installed to stabilize the bank of the erosional channel and manage stormwater erosion within the project area. Corrected run-off issue and added Rip-Rap in gully.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: James Javernick

Signed: \_\_\_\_\_

Title: Owner

Date: 12/3/2019 2:16:50 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402239870	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files