



State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303) 894-2100 Fax: (303) 894-2109



FOR OGCC USE ONLY

BRADENHEAD TEST REPORT

Step 1. Record all tubing and casing pressures as found.
Step 2. Sample now, if intermediate or surface casing pressure >25 psi. In sensitive areas, 1 psi.
Step 3. Conduct Bradenhead test.
Step 4. Conduct intermediate casing test.
Step 5. Send report to BLM within 30 days and to OGCC within 10 days. Include wellbore diagram if not previously submitted or if wellbore configuration has changed since prior program. Attach gas and liquid analyses if sampled.

1. OGCC Operator Number: <u>10672</u>	3. BLM Lease No: _____
2. Name of Operator: <u>TIM BEECHER</u>	5. Multiple completion? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
4. API Number: <u>05-071-09099</u>	6. Well Name: <u>ACOL-11</u>
7. Location (QtrQtr, Sec, Twp, Rng, Meridian): <u>NESW 01-11-68W</u>	9. Field Name: <u>PURVIS RIVER</u>
8. County: <u>LAS ANIMAS</u>	10. Minerals: <input checked="" type="checkbox"/> Fee <input type="checkbox"/> State <input type="checkbox"/> Federal <input type="checkbox"/> Indian

11. Date of Test: <u>3-5-20</u>
12. Well Status: <input checked="" type="checkbox"/> Flowing <input type="checkbox"/> Shut In
<input type="checkbox"/> Gas Lift <input type="checkbox"/> Pumping <input type="checkbox"/> Injection
<input type="checkbox"/> Clock/Intermittent
<input type="checkbox"/> Plunger Lift
13. Number of Casing Strings: <input checked="" type="checkbox"/> Two <input type="checkbox"/> Three <input type="checkbox"/> Liner?

STEP 1: EXISTING PRESSURES				
Record all pressures as found	Tubing: <u>0</u>	Prod. Casing: <u>-7</u>	Intermediate Csg: _____	Surface Casing: _____
	Fm: _____	Fm: _____		

15. STEP 2: See instructions above.

STEP 3: BRADENHEAD TEST					
Buried valve? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Confirmed open? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Elapsed Time (Min:Sec)	Fm: _____	Fm: _____	Production Casing PSIG	Intermediate Casing PSIG
With gauges monitoring production, intermediate casing and tubing pressures, open surface casing (bradenhead) valve (if no intermediate casing, monitor only the production casing and tubing pressures.) Record pressures at five minute intervals. Define characteristics of flow in "Bradenhead Flow" column using letter designations below: D = No Flow; C = Continuous; D = Down to 0; V = Vapor H = Water H2O; M = Mud; W = Whisper; S = Surge; G = Gas	00:	0		-7	0
	05:	0		-7	0
	10:	0		-7	0
	15:	0		-7	0
	20:	0		-7	0
	25:	0		-7	0
30:	0		-7	0	
BRADENHEAD SAMPLE TAKEN? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Gas <input type="checkbox"/> Liquid	Note instantaneous Bradenhead PSIG at end of test: > 0				

STEP 4: INTERMEDIATE CASING TEST					
Buried valve? <input type="checkbox"/> Yes <input type="checkbox"/> No Confirmed open? <input type="checkbox"/> Yes <input type="checkbox"/> No	Elapsed Time (Min:Sec)	Fm: _____	Fm: _____	Production Casing PSIG	Intermediate Casing PSIG
With gauges monitoring production casing and tubing pressures, open the intermediate casing valve. Record pressures at five minute intervals. Characterize flow in "Intermediate Flow" column using letter designations below: D = No Flow; C = Continuous; D = Down to 0; V = Vapor H = Water H2O; M = Mud; W = Whisper; S = Surge; G = Gas	00:				
	05:				
	10:				
	15:				
	20:				
	25:				
30:					
INTERMEDIATE SAMPLE TAKEN? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Gas <input type="checkbox"/> Liquid	Note instantaneous Intermediate Casing PSIG at end of test: >				

18. Comments: _____

19. STEP 5: See instructions above

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.
Test Performed by: M. MESSOMAR Title: Automation Phone: 719-859-3686
Signed: _____ Title: _____ Date: _____
WITNESSED BY: _____ Title: _____ Agency: _____