

FORM 6

Rev 02/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

402246425

Date Received:

11/21/2019

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 69175 Contact Name: Valerie Danson
Name of Operator: PDC ENERGY INC Phone: (970) 506-9272
Address: 1775 SHERMAN STREET - STE 3000 Fax:
City: DENVER State: CO Zip: 80203 Email: valerie.danson@pdce.com

For "Intent" 24 hour notice required, Name: Tel:
COGCC contact: Email:

Type of Well Abandonment Report: [] Notice of Intent to Abandon [X] Subsequent Report of Abandonment

API Number 05-123-12790-00 Well Name: SKURICH-ROTHE Well Number: 12-6
Location: QtrQtr: SWNW Section: 6 Township: 5N Range: 63W Meridian: 6
County: WELD Federal, Indian or State Lease Number: 65534
Field Name: WATTENBERG Field Number: 90750

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.430420 Longitude: -104.486060
GPS Data: GPS Quality Value: 3.5 Type of GPS Quality Value: PDOP Date of Measurement: 01/27/2007
GPS Instrument Operator's Name: Holly L. Tracy
Reason for Abandonment: [] Dry [] Production Sub-economic [] Mechanical Problems
[] Other
Casing to be pulled: [] Yes [] No Estimated Depth:
Fish in Hole: [] Yes [] No If yes, explain details below
Wellbore has Uncemented Casing leaks: [] Yes [] No If yes, explain details below
Details:

Current and Previously Abandoned Zones

Table with 6 columns: Formation, Perf. Top, Perf. Btm, Abandoned Date, Method of Isolation, Plug Depth. Row 1: NIOBRARA-CODELL, 6460, 6742, 10/30/2019, B PLUG CEMENT TOP, 6410

Total: 1 zone(s)

Casing History

Table with 9 columns: Casing Type, Size of Hole, Size of Casing, Weight Per Foot, Setting Depth, Sacks Cement, Cement Bot, Cement Top, Status. Rows: SURF, 1ST, S.C. 1.1

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 6410 with 2 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 40 sks cmt from 5478 ft. to 4978 ft. Plug Type: CASING Plug Tagged:
 Set 10 sks cmt from 3921 ft. to 3800 ft. Plug Type: CASING Plug Tagged:
 Set 35 sks cmt from 1712 ft. to 1200 ft. Plug Type: CASING Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)
 Set 55 sacks half in. half out surface casing from 624 ft. to 0 ft. Plug Tagged:
 Set _____ sacks at surface
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
 Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. _____ inch casing Cut and Cap Date: 10/31/2019
 of _____
 *Wireline Contractor: Ranger Energy Services *Cementing Contractor: C&J Energy Services
 Type of Cement and Additives Used: Class G 15.8 PPG Cement & Type III 14.8 PPG Portland Cement
 Flowline/Pipeline has been abandoned per Rule 1105 Yes No

Technical Detail/Comments:

Skurich-Rothe 12-6 (05-123-12790)/Plugging Procedure
 Producing Formation: Niobrara/Codell: 6460'-6742'
 Upper Pierre Aquifer: 335'-1405'
 TD: 6830' PBTD: 6798.3'
 Surface Casing: 8 5/8" 24# @300' w/ 250 sxs cmt
 Production Casing: 4 1/2" 11.6# @ 6830' w/ 200 sxs cmt calculated (TOC @ 6089' - CBL).
 Annular Fill with Casing Patch @ 5228' w/ 1205 sxs cmt (5612'-surface' - CBL).

Procedure:
 1. MIRU pulling unit. Pull 2 3/8" tubing.
 2. RU wireline company.
 3. TIH with CIBP. Set BP at 6410'. Top with 2 sxs 15.8#/gal CI G cement.
 4. TIH with tubing to 5478'. RU cementing company. Mix and pump 40 sxs 15.8#/gal CI G cement down tubing. (Casing Patch coverage from 5478'-4978'). TOC at 4978'.
 5. Pickup tubing to 3921'. Mix and pump 10 sxs 15.8#/gal CI G cement down tubing. TOC at 3800'.
 6. Pickup tubing to 1712'. Mix and pump 35 sxs 14.8#/gal Type III cement down tubing. (Pierre coverage from 1700'-1200'). TOC at 1200'.
 7. Pickup with tubing to 624'. Mix and pump 55 sxs 14.8#/gal Type III cement down tubing. Cement circulate to surface.
 8. Cut surface casing 6' below ground level and weld on cap.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Valerie Danson
 Title: Reg Tech Date: 11/21/2019 Email: valerie.danson@pdce.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved, Eric

COGCC Approved:

Date: 3/10/2020

CONDITIONS OF APPROVAL, IF ANY:

COA Type

Description

| | |
|--|--|
| | |
|--|--|

Attachment Check List

Att Doc Num

Name

| | |
|-----------|-----------------------------|
| 402246425 | FORM 6 SUBSEQUENT SUBMITTED |
| 402246456 | CEMENT JOB SUMMARY |
| 402246458 | OPERATIONS SUMMARY |
| 402246459 | WELLBORE DIAGRAM |

Total Attach: 4 Files

General Comments

User Group

Comment

Comment Date

| | | |
|--|--|---------------------|
| | | Stamp Upon Approval |
|--|--|---------------------|

Total: 0 comment(s)