

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402270293

Date Received:  
12/23/2019

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 10663

Name of Operator: ENDURING RESOURCES LLC

Address: 1050 17TH STREET SUITE 2500

City: DENVER State: CO Zip: 80265

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Felix, Andrea

afelix@enduringresources.com

Walter, Kyle

kwalter@enduringresources.com

Pohl, April

apohl@enduringresources.com

Huntington, Heather

hhuntington@enduringresources.com

**COGCC INSPECTION SUMMARY:**

FIR Document Number: 693901129

Inspection Date: 11/14/2019

FIR Submit Date: 12/05/2019

FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: ENDURING RESOURCES LLC

Company Number: 10663

Address: 1050 17TH STREET SUITE 2500

City: DENVER State: CO Zip: 80265

**LOCATION - Location ID: 326275**

Location Name: LAPALOMA-N34N9W Number: 1NENW County: LA PLATA

Qtrqtr: NENW Sec: 1 Twp: 34N Range: 9W Meridian: N

Latitude: 37.240972 Longitude: -107.805710

**FACILITY - API Number: 05-067- -00 Facility ID: 216152**

Facility Name: LAPALOMA Number: 1-2

Qtrqtr: NENW Sec: 1 Twp: 34N Range: 9W Meridian: N

Latitude: 37.240972 Longitude: -107.805710

**CORRECTIVE ACTIONS:**

**1**  CA# 135101

Corrective Action: Remove and control weeds.

Date: 12/20/2020

Response: CA COMPLETED

Date of Completion: 12/20/2019

Enduring Resources is obligated to the surface owner not to remove the referenced Russian Olive Trees as they are a requirement from the surface owner to Enduring per the SUA. The SUA required the operator to plant

Operator Comment: Russian Olive Trees, 15 feet apart on side of the well pad exposed to the subdivision. Enduring will be in violation of the SUA with the surface owner if these trees are removed.

COGCC Decision: **Not Approved**

COGCC Representative: COGCC recommends planting trees that are not noxious weeds and communicating with surface owner the importance of not spreading/planting noxious weeds. Operator comment does not indicate that corrective action is addressed.

2 ☒ CA# 135102

Corrective Action: Stormwater BMPs need maintenance and repair/replacement.

Date: 12/20/2019

Response: CA COMPLETED

Date of Completion: 12/20/2019

Operator Comment: SEE ATTACHED PHOTOS

COGCC Decision: Approved pending re-inspection

COGCC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Heather Huntington

Signed:

Title: Permitting Technician

Date: 12/23/2019 11:57:14 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402270293	FIR RESOLUTION SUBMITTED
402270310	CA PHOTOS

Total Attach: 2 Files