

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/14/2020

Submitted Date:

03/16/2020

Document Number:

699600427

FIELD INSPECTION FORM
 Loc ID 312302 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Eisterhold, Racheal		regulatory@foundationenergy.com	N.E. Colo. inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221141	WELL	SI	07/01/2019	OW	075-09267	BANEY-STATE 16-5	SI

General Comment:

Routine Site FIR

Note to Operator:

Corrective Action cited within this FIR, read completely and perform CA within designated date. Please notify N.E. Field Inspector via Form 42 when work is complete and ready for re-inspection.

Location				
Lease Road:				
Type	Access			
comment:	Two track cropland			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	OTHER			
Comment:	Install highly visible markers @ all deadman - min. (4') in height.			
Corrective Action:	Install proper guy line anchor markers per Rule 1003.a			Date: 03/31/2020
Type	WELLHEAD			
Comment:	Satisfactory			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Satisfactory			
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Heavy expanded steel wire around moving parts.			
Corrective Action:				Date:
Equipment:				
				corrective date
Type: Other	# 0			
Comment:	No change in equipment inventoried			
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment:	Install highly visible anchor markers. See attached photograph for documentation.			
Corrective Action:	Properly install guy line anchor markers per Rule 1003.a			Date: 03/31/2020
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				

Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 221141 Type: WELL API Number: 075-09267 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Routine Site FIR - CA cited for deadman markers. SI status since 7/01/2019

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: Located within rotational cropland with rotational tillage.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<u>Note to Operator: Corrective Action required, read FIR completely and perform actions within designated dates required.</u>	schureky	03/16/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402344338	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5097599
699600453	PJ - Wellhead - Signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5097586
699600454	Unmarked deadman	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5097587