

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402282703

Date Received:

01/13/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10464

Name of Operator: CATAMOUNT ENERGY PARTNERS LLC

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Recipient, Single

Inspections@catamountep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901052

Inspection Date: 11/01/2019

FIR Submit Date: 11/08/2019

FIR Status: _____

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC

Company Number: 10464

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 320848

Location Name: FEDERAL-M34N6W Number: 26SWSW County: ARCHULETA

Qtrqr: SWS Sec: 26 Twp: 34N Range: 6W Meridian: M
W

Latitude: 37.157850 Longitude: -107.475640

FACILITY - API Number: 05-007- -00 Facility ID: 205218

Facility Name: FEDERAL Number: 26-1

Qtrqr: SWS Sec: 26 Twp: 34N Range: 6W Meridian: M
W

Latitude: 37.157850 Longitude: -107.475640

CORRECTIVE ACTIONS:

1 ☒ CA# 134385

Corrective Action: Stormwater controls that are sufficient to stabilize erosion and prevent sediment discharge from the project area are needed within the southwestern project area. Corrective action date is the date of the inspection as it is the expectation that the location be stabilized at the time of inspection.

Date: 11/01/2019

Response: CA COMPLETED

Date of Completion: 12/20/2019

Catamount Energy partners and Cottonwood Consulting have had many onsite meetings and consultations with the USFS IDT team about proper stormwater management and BMP development for this pad. Additional sediment control logs were added to the fill slope on 11/22/2019. Please see attached inspection email from

Operator Comment: USFS on 12/3/2019. Catamount Energy partners and Cottonwood Consulting had calls on 12/10/2019 and 12/17/2019 with Walt Brown at USFS about proper BMP measures before winter closure. BMP installs were complete by 12/20.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nolan Redmond

Signed: _____

Title: Geo/Eng Tech

Date: 1/13/2020 12:53:28 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402282703	FIR RESOLUTION SUBMITTED
402283783	BMP Map
402283785	USFS Inspection

Total Attach: 3 Files