

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402282847

Date Received:

01/10/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10464

Name of Operator: CATAMOUNT ENERGY PARTNERS LLC

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Recipient, Single

Inspections@catamountep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900926

Inspection Date: 10/08/2019

FIR Submit Date: 10/17/2019

FIR Status: _____

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC

Company Number: 10464

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 320863

Location Name: PARGIN MOUNTAIN UNIT Number: M34N5W /34NESW County: ARCHULETA

Qtrqtr: NESW Sec: 34 Twp: 34N Range: 5W Meridian: M

Latitude: 37.146900 Longitude: -107.382320

FACILITY - API Number: 05-007- -00 Facility ID: 205261

Facility Name: PARGIN MOUNTAIN UNIT Number: 11

Qtrqtr: NESW Sec: 34 Twp: 34N Range: 5W Meridian: M

Latitude: 37.146900 Longitude: -107.382320

CORRECTIVE ACTIONS:

1 ☒ CA# 131761

Corrective Action: Interim reclamation needs to be conducted during the fall 2019 seeding window. Topsoil that is retained for final reclamation shall be protected using short term and long term stabilization methods, such as use of straw mulch crimped into the soil, stormwater controls, and revegetation. Corrective action is backdated to start of construction date as topsoil protection should be initiated at that time.

Date: 09/10/2018

Response: CA COMPLETED

Date of Completion: 11/18/2019

Lowered topsoil pile and reclaimed.

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 131762

Corrective Action: Bare soils on well pad cut-slope need to be stabilized.

Date: 10/31/2019

Response: CA COMPLETED

Date of Completion: 11/18/2019

Operator
Comment:

Finished wellpad and cut slope reclamation

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nolan Redmond

Signed: _____

Title: Geo/Eng Tech

Date: 1/10/2020 4:26:19 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402282847	FIR RESOLUTION SUBMITTED
402282853	Remedial Report

Total Attach: 2 Files