

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402360780

Date Received:

04/03/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 74165

Name of Operator: RENEGADE OIL & GAS COMPANY LLC

Address: 6155 S MAIN STREET #225

City: AURORA State: CO Zip: 80016

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Ingve, Ed</u>	<u>303-829-2354</u>	<u>ed@renegadeoilandgas.com</u>
<u>Condill, JB</u>	<u>303-680-4725</u>	<u>jbcrog@aol.com</u>
<u>Espinosa, Bill</u>	<u>(303) 829-4982</u>	<u>billespinosa30@yahoo.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 688306744

Inspection Date: 01/09/2020

FIR Submit Date: 01/14/2020

FIR Status: _____

Inspected Operator Information:

Company Name: RENEGADE OIL & GAS COMPANY LLC

Company Number: 74165

Address: 6155 S MAIN STREET #210

City: AURORA State: CO Zip: 80016

LOCATION - Location ID: 320683

Location Name: STATE OF COLO 'T' NCT-3-65S65W Number: 25SWNE County: ARAPAHOE

Qtrqr: SWNE Sec: 25 Twp: 5S Range: 65W Meridian: 6

Latitude: 39.589270 Longitude: -104.611350

FACILITY - API Number: 05-005- -00

Facility ID: 204455

Facility Name: STATE OF COLO 'T' NCT-3 Number: 1

Qtrqr: SWNE Sec: 25 Twp: 5S Range: 65W Meridian: 6

Latitude: 39.589270 Longitude: -104.611350

CORRECTIVE ACTIONS:

1 ☒ CA# 135967

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes.

Date: 01/22/2020

Response: CA COMPLETED

Date of Completion: 03/30/2020

Engine oil stained soil has been removed and replaced. Engine is scheduled to be replaced with a rebuilt engine

Operator
Comment: shortly. Delay caused by weather and mud.

COGCC Decision: Approved

COGCC
Representative: Per this FIRR work was completed later in the day of original inspection, reinspection was done on 4/3/2020 and original inspection was modified.

OPERATOR COMMENT AND SUBMITTAL

Comment: Delay in addressing the stained soil caused by weather, mud and crew availability. Engine is scheduled to be rotated with a rebuilt engine.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edward Ingve

Signed: _____

Title: Manager/Owner

Date: 4/3/2020 9:02:16 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402360780	FIR RESOLUTION SUBMITTED
402360793	Stained soil removed
402360794	Stained soil removed

Total Attach: 3 Files