

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402362826

Date Received:

04/06/2020

## FIR RESOLUTION FORM

Overall Status: CAC

### CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name	Phone	Email
<u>Beebe, Sabre</u>	<u>970-779-9398</u>	<u>Sabre.Beebe@bpx.com</u>
<u>Inspections, All</u>		<u>SanJuanCOGCC@bp.com</u>
<u>Fischer, Alex</u>		<u>alex.fischer@state.co.us</u>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 688800506  
Inspection Date: 04/18/2019 FIR Submit Date: 05/08/2019 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

### LOCATION - Location ID: 306865

Location Name: LEROY MCCA W GAS UNIT B- M34N8W Number: 21NWSE County: LA PLATA  
Qtrqtr: NWSE Sec: 21 Twp: 34N Range: 8W Meridian: M  
Latitude: 37.173543 Longitude: -107.718506

### FACILITY - API Number: 05-067- -00 Facility ID: 270614

Facility Name: LEROY MCCA W B Number: 2  
Qtrqtr: NWSE Sec: 21 Twp: 34N Range: 8W Meridian: M  
Latitude: 37.173543 Longitude: -107.718506

### CORRECTIVE ACTION:

**1** CA# 124994

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a Contact COGCC EPS staff.

Date: 06/07/2019

Response: CA COMPLETED

Date of Completion: 04/02/2020

Verified all work on corrective action completed on location. Bull plug replaced and tightened on load line to prevent future impacts. Impacts removed from location and sent to IEI in NM for bulk remediation in BPX soil

Operator Comment: box. Back fill of all impact removal areas. Location dragged to smooth out ruts.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

2 CA# 124995

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 06/07/2019

Response: CA COMPLETED

Date of Completion: 04/02/2020

Operator Comment: Verified all work on corrective action completed on location. Bull plug replaced and tightened on load line to prevent future impacts. Impacts removed from location and sent to IEI in NM for bulk remediation in BPX soil box. Back fill of all impact removal areas. Location dragged to smooth out ruts.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions verified as complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe Signed: \_\_\_\_\_

Title: Specialist Date: 4/6/2020 12:18:31 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402362845	completion verification form

Total Attach: 1 Files