

Document Number:
402365999

Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 72400 Contact Name: Jeff Schneider

Name of Operator: PUBLIC SERVICE COMPANY OF COLORADO Phone: (970) 867-9437

Address: 1123 W 3RD AVE Fax: _____

City: DENVER State: CO Zip: 80223 Email: jeff@schneiderenergy.com

For "Intent" 24 hour notice required, Name: Browning, Chuck Tel: (970) 433-4139

COGCC contact: Email: chuck.browning@state.co.us

Type of Well Abandonment Report: Notice of Intent to Abandon Subsequent Report of Abandonment

API Number 05-077-05093-00

Well Name: ASBURY STORAGE UNIT-FED Well Number: 4

Location: QtrQtr: SWNE Section: 14 Township: 9S Range: 101W Meridian: 6

County: MESA Federal, Indian or State Lease Number: _____

Field Name: ASBURY CREEK Field Number: 3200

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.275760 Longitude: -108.629390

GPS Data: GPS Quality Value: 0.1 Type of GPS Quality Value: PDOP Date of Measurement: 05/18/2006

GPS Instrument Operator's Name: Paul Kellogg

Reason for Abandonment: Dry Production Sub-economic Mechanical Problems

Other This is a observation well in a gas storage field that is no longer

Casing to be pulled: Yes No Estimated Depth: _____

Fish in Hole: Yes No If yes, explain details below

Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below

Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
DAKOTA	2777	2810		CEMENT	

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	539	375	539	0	VISU
1ST	6+3/4	4+1/2	9.5	2,777	135	2,777	757	CALC

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIPB #2: Depth _____ with _____ sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIPB #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 75 sks cmt from 2810 ft. to 2677 ft. Plug Type: OPEN HOLE Plug Tagged:
 Set 35 sks cmt from 50 ft. to 0 ft. Plug Type: CASING Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at 589 ft. with 50 sacks. Leave at least 100 ft. in casing 489 CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:
 Set _____ sacks at surface
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
 Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. _____ inch casing Cut and Cap Date: _____
 of _____
 *Wireline Contractor: _____ *Cementing Contractor: _____
 Type of Cement and Additives Used: _____
 Flowline/Pipeline has been abandoned per Rule 1105 Yes No

Technical Detail/Comments:
 There is an open hole sections in this well from 2810' to 2777' that will be filled with 75 sacks of cement and that plug will be tagged.
 There is No CBL on file for this well. The plan is to pump the open hole plug, wait 4 hours, then tag it. If the plug top is at an exceptable depth we will pressure test the casing and plug to 500 psi. TOO with tubing and then run a CBL. The CBL will be emailed to the COGCC engineer and BLM engineer and we will not proceed with the plugging operations until given approval by both. A copy of the CBL will be submitted with the final form 6.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.
 Signed: _____ Print Name: Jeff Schneider
 Title: Consultant Date: _____ Email: jeff@schneiderenergy.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: _____

COA Type	Description

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
402366007	WELLBORE DIAGRAM
402366011	WELLBORE DIAGRAM
402366021	OTHER

Total Attach: 3 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)