

APACHE CANYON 18-09 API# 05-071-06339 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 08, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200125



PHOTO 1: THE IMPACTED SOIL IN FRONT OF THE DRIP RISER WAS CLEANED UP.

APACHE CANYON 18-09 API# 05-071-06339 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 08, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200125



PHOTO 2: THE IMPACTED SOIL IN FRONT OF THE DRIP RISER WAS CLEANED UP.

APACHE CANYON 18-09 API# 05-071-06339 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 08, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200125



PHOTO 3: THE IMPACTED SOIL ALONG THE BAR DITCH WAS CLEANED UP.

APACHE CANYON 18-09 API# 05-071-06339 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 08, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200125



PHOTO 4: THE IMPACTED SOIL ALONG THE BAR DITCH WAS CLEANED UP.

APACHE CANYON 18-09 API# 05-071-06339 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 08, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690200125



PHOTO 5: THE IMPACTED SOIL ALONG THE BAR DITCH WAS CLEANED UP.