

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402307161

Date Received:

02/10/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10464

Name of Operator: CATAMOUNT ENERGY PARTNERS LLC

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Recipient, Single

Inspections@catamountep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901367

Inspection Date: 01/22/2020

FIR Submit Date: 01/24/2020

FIR Status: _____

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC

Company Number: 10464

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 326237

Location Name: JAQUES-N33N8W Number: 27NWSE County: LA PLATA

Qtrqr: NWSE Sec: 27 Twp: 33N Range: 8W Meridian: N

Latitude: 37.071726 Longitude: -107.700364

FACILITY - API Number: 05-067- -00 Facility ID: 454846

Facility Name: Jaques Number: 11

Qtrqr: NWSE Sec: 27 Twp: 33N Range: 8W Meridian: N

Latitude: 37.071726 Longitude: -107.700364

CORRECTIVE ACTIONS:

1 ☒ CA# 136134

Corrective Action: Remove and properly dispose of metal debris.

Date: 02/07/2020

Response: CA COMPLETED

Date of Completion: 02/06/2020

Operator Comment: Removed and disposed of metal debris.

COGCC Decision: Approved pending re-inspection

COGCC
Representative: _____

2 ☒ CA# 136135

Corrective Action: Conduct revegetation throughout the interim reclamation areas. Weeds need to be controlled.

Date: 11/12/2019

Response: CA COMPLETED

Date of Completion: 02/06/2020

Operator Comment: Removed and disposed of weed debris, reseeded and applied straw mulch on bare cut slope, Will seed and mulch remaining slope when snow melts.

COGCC Decision: Approved pending re-inspection

COGCC
Representative: _____

3 ☒ CA# 136136

Corrective Action: Stormwater controls (ie BMPs) and erosion controls (ie mulching/blankets, revegetation etc.) are needed to stabilize soils within the project area. Stormwater controls need to be selected, sized, installed, and maintained in accordance with good engineering practices such as those described by CDOT in their erosion control manuals.

Date: 11/12/2019

Response: CA COMPLETED

Date of Completion: 02/06/2020

Operator Comment: Installed drainage ditch at the top of the cut slope with rock catch basins at the outlets for storm water and erosion control. Installed straw mulch on bare slope.

COGCC Decision: Approved pending re-inspection

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nolan Redmond

Signed: _____

Title: Geo/Eng Tech

Date: 2/10/2020 7:37:09 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402307161	FIR RESOLUTION SUBMITTED
402307165	Remedial Report

Total Attach: 2 Files