

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402360744

Date Received:

04/02/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Beebe, Sabre

sabre.beebe@bpx.com

SanJuanCOGCC@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901412

Inspection Date: 02/10/2020

FIR Submit Date: 02/12/2020

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 333471

Location Name: H N PEARSON A-M34N7W Number: 20SWNW County: _____

Qtrqr: SWN Sec: 20 Twp: 34N Range: 7W Meridian: M
W

Latitude: 37.179008 Longitude: -107.637704

FACILITY - API Number: 05-067- -00 Facility ID: 333471

Facility Name: H N PEARSON A-M34N7W Number: 20SWNW

Qtrqr: SWN Sec: 20 Twp: 34N Range: 7W Meridian: M
W

Latitude: 37.179008 Longitude: -107.637704

CORRECTIVE ACTIONS:

1 ☒ CA# 136497

Corrective Action: Remove waste and debris. Corrective action is backdated to document duration of non-compliance.

Date: 04/30/2017

Response: CA COMPLETED

Date of Completion: 03/20/2020

Operator Comment: Waste and debris cited in the inspection belonged to the landowner and legally BPX could not remove the debris and dispose of it without landowner authorization. Negotiations with the landowner and the reoccurring problem of encroachment has resulted in BPX having the landowner move their items and BPX installing fencing in an

attempt to stop future encroachment. Debris has been moved by landowner and fencing installed see attached.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions completed. Work completion delayed due to landowner belongings not being able to legally be moved and/or disposed of by BPX without authorization. Had to work with landowner to move their items off the well pad. Encroachment has been on going issue so a fence has been installed to delineate well pad.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Specialist

Date: 4/2/2020 4:15:53 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402360744	FIR RESOLUTION SUBMITTED
402360804	Closure document

Total Attach: 2 Files