

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402381126

Date Received:  
04/27/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 5 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 100 CHEVRON ROAD

City: RANGELY State: CO Zip: 81648

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Chris Patteson</u>	<u>970-675-3814</u>	<u>SPWU@chevron.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696200925

Inspection Date: 01/28/2020

FIR Submit Date: 01/29/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 100 CHEVRON ROAD

City: RANGELY State: CO Zip: 81648

LOCATION - Location ID: 398839

Location Name: UNION PACIFIC Number: 150,151,152 County: \_\_\_\_\_  
,153

Qtrqtr: NW Sec: 16 Twp: 2N Range: 102W Meridian: 6  
SW

Latitude: 40.141408 Longitude: -108.857053

FACILITY - API Number: 05-103-00 Facility ID: 398839

Facility Name: UNION PACIFIC Number: 150,151,152  
,153

Qtrqtr: NW Sec: 16 Twp: 2N Range: 102W Meridian: 6  
SW

Latitude: 40.141408 Longitude: -108.857053

CORRECTIVE ACTIONS:

**3** CA# 136208

Corrective Action: Comply with Rule 308A.b.(2)F and submit correct "as drilled" latitude and longitude coordinates within a Form 4 Sundry.

Date: 02/29/2020

Response: CA COMPLETED

Date of Completion: 02/05/2020

Operator Comment: Sent in Form 4 Sundry Doc # 402303897

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**5** CA# 136210

Corrective Action: Comply with Rule 1003.b; Conduct reclamation on areas of the Location not reasonably needed for production activities. Additionally, If it is determined that if vegetative establishment on the current interim areas is not progressing towards Rule 1003.e.(2) standards, then Operator is directed to conduct additional reclamation on these areas as needed. Ensure erosion and stabilization BMPs are implemented to stabilize the reclamation areas, and remaining production area, pursuant to rule 1002.f.

Date: 04/01/2020

Response: CA COMPLETED

Date of Completion: 02/19/2020

Operator  
Comment:

Completed through the Chevron Work Order System by the Colorado Area Planner. Work for resizing the pad will be discussed with our reclamation Subject Matter Experts and added to the Q.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Completed through the Chevron Work Order System by the Colorado Area Planner.c

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Patterson

Signed: \_\_\_\_\_

Title: HES Specialist

Date: 4/27/2020 9:57:18 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files