

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402378149

Date Received:

04/22/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Fitzgerald, Edie

ediefitzgerald@tcenergyllc.com

Mack, Ronald

ronaldmack@tcenergyllc.com

BAKER DAVID

dbaker@auroramp.com

Dylan Thomsen

timothy.thomsen@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901925

Inspection Date: 03/19/2020

FIR Submit Date: 03/20/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 333911

Location Name: NEW ELK-633S68W Number: 36NESW County: LAS ANIMAS

Qtrqtr: NESW Sec: 36 Twp: 33S Range: 68W Meridian: 6

Latitude: 37.126110 Longitude: -104.949580

FACILITY - API Number: 05-071- -00 Facility ID: 276687

Facility Name: NEW ELK Number: 36-11

Qtrqtr: NESW Sec: 36 Twp: 33S Range: 68W Meridian: 6

Latitude: 37.126110 Longitude: -104.949580

CORRECTIVE ACTIONS:

1 ☒ CA# 137334

Corrective Action: Repair and maintain lease road.

Date: 04/17/2020

Response: CA COMPLETED

Date of Completion: 04/21/2020

The sediment accumulation was removed from the culvert inlet. The lease road was regraded to eliminate the tire

Operator Comment: ruts and establish sheet flow. The surface erosion along the main access road was corrected by surface crowning which creates sheet flow. See attached photo log for details.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 ☒ CA# 137335

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 04/17/2020

Response: CA COMPLETED

Date of Completion: 04/21/2020

Operator Comment: The large rock was pushed off of the driving surface. The main lease road was regraded to eliminate the tire ruts and establish sheet flow. See attached photo log for details.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: \_\_\_\_\_

Title: SR. Environmental Tech.

Date: 4/22/2020 3:00:34 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402378149	FIR RESOLUTION SUBMITTED
402378207	Photo Log

Total Attach: 2 Files