

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402387690

Date Received:
05/01/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>
<u>Ray, Mandy</u>	<u>(505) 599-4083</u>	<u>mray@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901604

Inspection Date: 04/03/2020

FIR Submit Date: 04/06/2020

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 333865

Location Name: PACHECO 32-7-N32N7W Number: 12SESW County: LA PLATA

Qtrqr: SESW Sec: 12 Twp: 32N Range: 7W Meridian: N

Latitude: 37.027760 Longitude: -107.563690

FACILITY - API Number: 05-067-00 Facility ID: 263202

Facility Name: PACHECO 32-7 Number: 12-3

Qtrqr: SESW Sec: 12 Twp: 32N Range: 7W Meridian: N

Latitude: 37.027760 Longitude: -107.563690

CORRECTIVE ACTIONS:

1 CA# 137730

Corrective Action: Remove and properly dispose of weed debris.

Date: 04/20/2020

Response: CA COMPLETED

Date of Completion: 04/29/2020

Operator Comment: Weed debris were removed. See attached photos.

COGCC Decision: _____

COGCC Representative:			
2	CA# 137731		
Corrective Action:	Revegetation needs to be conducted within the majority of the interim reclamation areas, where little desirable vegetation is present.	Date: <u>05/01/2020</u>	
Response:	CA COMPLETED	Date of Completion: <u>04/29/2020</u>	
Operator Comment:	Revegetation was conducted. See attached photos.		
COGCC Decision:			
COGCC Representative:			
3	CA# 137732		
Corrective Action:	-Erosion controls (such as mulch) and stormwater controls (such as BMPs) are needed within the project area until interim reclamation areas are stabilized with desirable perennial vegetation.	Date: <u>05/01/2020</u>	
Response:	CA COMPLETED	Date of Completion: <u>04/29/2020</u>	
Operator Comment:	Erosion controls were implemented within project area. See attached photos.		
COGCC Decision:			
COGCC Representative:			

<u>OPERATOR COMMENT AND SUBMITTAL</u>	
Comment:	
<p>I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.</p> <p>Print Name: <u>Priscilla Shorty</u> Signed: _____</p> <p>Title: <u>OperationsRegulatory Tech</u> Date: <u>5/1/2020 1:53:21 PM</u></p>	

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402387712	PACHECO 32-7 12-3_Resolved Photos

Total Attach: 1 Files