

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402392320

Date Received:
05/07/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Santistevan, Vince</u>	<u>719-845-2102/719-680-9705</u>	<u>vincasantistevan@tcenergyllc.com</u>
<u>Fitzgerald, Edie</u>	<u>719-859-1394</u>	<u>ediefitzgerald@tcenergyllc.com</u>
<u>Mack, Ronald</u>		<u>ronaldmack@tcenergyllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 695102767
Inspection Date: 04/30/2020 FIR Submit Date: 05/01/2020 FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 309441

Location Name: NEW ELK-633S68W Number: 25SENW County: LAS ANIMAS
Qtrqr: SENW Sec: 25 Twp: 33S Range: 68W Meridian: 6
Latitude: 37.144997 Longitude: -104.948571

FACILITY - API Number: 05-071-00 Facility ID: 295030

Facility Name: NEW ELK Number: 25-06
Qtrqr: SENW Sec: 25 Twp: 33S Range: 68W Meridian: 6
Latitude: 37.144997 Longitude: -104.948571

CORRECTIVE ACTIIONS:

1 CA# 138573

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. 5-7-20.

Date: 05/07/2020

Response: CA COMPLETED

Date of Completion: 05/06/2020

Operator Comment: Maintenance was conducted to stop the leak on the liquid ring compressor. The impacted soil around the liquid ring was removed from location. See attached photo log for details.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 138574

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes.

Date: 05/07/2020

Response: CA COMPLETED

Date of Completion: 05/06/2020

Operator Comment: Maintenance was conducted to stop the leak on the engine skid. The impacted soil was cleaned up and removed from location. See attached photo log for details.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 138575

Corrective Action: Comply with general provisions of the oil and gas act for wildlife protection. PRIME MOVER ENGINE SKID IS FULL OF FLUID AND ABOUT TO RUN OVER 24 HOURS TO CORRECT 5-7-20 FOR COMPRESSOR SKID.

Date: 05/07/2020

Response: CA COMPLETED

Date of Completion: 05/01/2020

Operator Comment: The fluid accumulation in the containment below the PC engine was removed. See attached photo log for details.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 5/7/2020 10:48:09 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number Description

402392344	Photo Log
-----------	-----------

Total Attach: 1 Files