

NEW ELK 25-06 API# 05-071-09536 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: MAY 01, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102767



PHOTO 1: THE FLUID ACCUMULATION WAS REMOVED FROM THE ENGINE CONTAINMENT AT 2:45 PM 05/01/20 APPROXIMATELY 3 HOURS AFTER NOTIFICATION.

NEW ELK 25-06 API# 05-071-09536 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: MAY 01, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102767



PHOTO 2: THE FLUID ACCUMULATION WAS REMOVED FROM THE CONTAINMENT BELOW THE ENGINE.

NEW ELK 25-06 API# 05-071-09536 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: MAY 06, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102767



PHOTO 3: THE FLUID ACCUMULATION WAS REMOVED FROM THE CONTAINMENT OF THE LIQUID RING COMPRESSOR AND THE SKID WAS CLEANED

NEW ELK 25-06 API# 05-071-09536 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: MAY 06, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102767



PHOTO 4: THE IMPACTED SOIL/GRAVEL NEAR THE LIQUID RING COMPRESSOR WAS REMOVED FROM THE LOCATION.

NEW ELK 25-06 API# 05-071-09536 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: MAY 06, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102767



PHOTO 5: THE IMPACTED SOIL/GRAVEL NEAR THE LIQUID RING COMPRESSOR WAS REMOVED FROM THE LOCATION.

NEW ELK 25-06 API# 05-071-09536 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: MAY 06, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102767



PHOTO 6: THE IMPACTED SOIL/GRAVEL NEAR THE ENGINE SKID WAS REMOVED FROM THE LOCATION.

NEW ELK 25-06 API# 05-071-09536 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: MAY 06, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102767



PHOTO 7: THE CONTAINMENT BELOW THE PC ENGINE WAS CLEANED.