

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402392362

Date Received:
05/07/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Santistevan, Vince</u>	<u>719-845-2102/719-680-9705</u>	<u>vincasantistevan@tcenergyllc.com</u>
<u>Fitzgerald, Edie</u>	<u>719-859-1394</u>	<u>ediefitzgerald@tcenergyllc.com</u>
<u>Mack, Ronald</u>		<u>ronaldmack@tcenergyllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 695102763
Inspection Date: 04/30/2020 FIR Submit Date: 04/30/2020 FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 309390

Location Name: NEW ELK-633S68W Number: 24SESE County: LAS ANIMAS
Qtrqr: SESE Sec: 24 Twp: 33S Range: 68W Meridian: 6
Latitude: 37.150971 Longitude: -104.941255

FACILITY - API Number: 05-071- -00 Facility ID: 294298

Facility Name: NEW ELK Number: 24-16
Qtrqr: SESE Sec: 24 Twp: 33S Range: 68W Meridian: 6
Latitude: 37.150971 Longitude: -104.941255

CORRECTIVE ACTIONS:

1 CA# 138567

Corrective Action: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A THIS IS SECOND NOTICE FOR THIS CORRECTIVE ACTION.

Date: 05/07/2020

Response: CA COMPLETED

Date of Completion: 05/06/2020

Operator Comment: The fluid accumulation in the containment below the PC engine was removed and the skid was cleaned. The fluid accumulation in the containment of the liquid ring compressor was removed and the skid was cleaned up. The impacted soil around the liquid ring was removed from location. See attached photo log for details.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 138568

Corrective Action: Comply with general provisions of the oil and gas act for wildlife protection.

Date: 05/07/2020

Response: CA COMPLETED

Date of Completion: 05/06/2020

Operator Comment: The fluid accumulation in the containment below the PC engine was removed and the skid was cleaned. The fluid accumulation in the containment of the liquid ring compressor was removed and the skid was cleaned up. The impacted soil around the liquid ring was removed from location. See attached photo log for details.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 5/7/2020 10:58:12 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402392373	Photo Log
-----------	-----------

Total Attach: 1 Files