

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402392717

Date Received:  
05/07/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>
<u>Ray, Mandy</u>	<u>(505) 599-4083</u>	<u>mray@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901214  
Inspection Date: 12/13/2019 FIR Submit Date: 12/17/2019 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 325300

Location Name: SQUIRES-N32N7W Number: 1NENE County: LA PLATA  
Qtrqtr: NENE Sec: 1 Twp: 32N Range: 7W Meridian: N  
Latitude: 37.051110 Longitude: -107.554590

FACILITY - API Number: 05-067-00 Facility ID: 214515

Facility Name: SQUIRES Number: 1  
Qtrqtr: NENE Sec: 1 Twp: 32N Range: 7W Meridian: N  
Latitude: 37.051110 Longitude: -107.554590

CORRECTIVE ACTIONS:

1 CA# 135394

Corrective Action: Revegetation needs to be installed by 4/1/2020. Weeds need to be controlled at the appropriate time but no later than 5/1/2020. Please note that herbicide application on young seedlings will likely adversely effect seedling establishment. Livestock exclusion appears needed for successful revegetation. Date: 05/01/2020

Response: CA COMPLETED Date of Completion: 05/04/2020

Operator Comment: Weeds removed. Re-contouring and control ditches installed. Revegetation with mulch is completed. See attached photos.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**2** CA# 135395

Corrective Action: Stormwater controls (ie BMPs) need to be installed immediately to stabilize erosion within the project area. Erosion controls ( ie mulching and erosion blankets) need to be installed at the time of seeding and no later than 4/1/2020. Stormwater erosion is documented on multiple inspections since 2015. Corective action is backdated to document duration of non-compliance since previous inspection.

Date: 10/10/2018

Response: CA COMPLETED

Date of Completion: 05/04/2020

Operator Comment: Weeds removed. Re-contouring and control ditches installed. Revegetation with mulch is completed. See attached photos.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: \_\_\_\_\_

Title: OperationsRegulatory Tech

Date: 5/7/2020 2:06:59 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

402392729	Squires 1_Resolved Photos
-----------	---------------------------

Total Attach: 1 Files