

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/28/2020

Submitted Date:

04/28/2020

Document Number:

699501196**FIELD INSPECTION FORM**Loc ID 320156 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 19035Name of Operator: OVERLAND RESOURCES LLCAddress: SUITE C18 PMB 440City: GREENWOOD State: CO Zip: 80121**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Anderson, Robert	303-800-6175	admin@overlandresourcesllc.com	
,		dnr_cogccenforcement@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	
Pandolfo, Chris	(650) 387-6506	cpandolfo@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202852	WELL	SI	07/01/2017	OW	001-08257	THOMPSON-PRICE 2	SI

General Comment:

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s) or battery		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	04/14/2017
Type	BATTERY		
Comment:	No Sign or label on water tank see pics		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	10/26/2018

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Inadequate berms around tank(s)		
Corrective Action:	n: Repair or install berms or other secondary containment devices per Rule 605.a.(4).	Date:	11/26/2018
Type	OTHER		
Comment:	Soiled dirt around Produced water tanks (fiberglass and steel). Stained soil under load out line to produced water tank (steel).		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	04/14/2017
Type	OTHER		
Comment:	Stained soil around pumping unit motor and gear box see pics		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	04/14/2017
Type	OTHER		
Comment:	Stained soil possible leak in separator house see pic 9		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	06/07/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Type: Vertical Heater Treater	# 1	
Comment:		
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment: gas motor		
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	Open Top		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	inadequate			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	inadequate berms			

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--

Inspected Facilities

Facility ID: 202852 Type: WELL API Number: 001-08257 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 4/28/2020 at approximately 1200 I, Inspector Justin Medina conducted an onsite inspection at Thompson Price #2 Overland Resources LLC 001-08257 in Adams County Colorado.</p> <p>While there, I observed Shut in well</p> <p>This is a follow up inspection from document # 685502197 & 688400480 & 685100925</p> <p>All Corrective Actions from previous 3 inspections have not been addressed and are delinquent as of 10/24/18</p> <p>Location is not accessible during normal business hours.</p> <p>Provide key, combinations, or alternate method of access to comply with rule 204.</p> <p>Sign or label not posted or information inaccurate on tanks or containers</p> <p>No placards on Pro Water fiberglass tank</p> <p>Install sign to comply with Rule 210.d.</p> <p>Stained soil around PU motor and gear box</p> <p>Properly treat or dispose of oily waste in accordance with 907.e.</p> <p>Soiled dirt around Produced water tanks (fiberglass and steel). Stained soil under load out line to produced water tank (steel).</p> <p>Properly treat or dispose of oily waste in accordance with 907.e.</p> <p>Stained soil possible leak in separator house see pic 9</p> <p>Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 6/7/19</p> <p>Inadequate berms around tank(s)</p> <p>Repair or install berms or other secondary containment devices per Rule 605.a.(4).</p> <p>Inadequate berms around tank(s)</p> <p>Repair or install berms or other sec</p>	medinaj	04/28/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699501197	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5146847