

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/29/2020

Submitted Date:

06/03/2020

Document Number:

697501591**FIELD INSPECTION FORM**Loc ID 441696 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10311Name of Operator: SRC ENERGY INCAddress: 1675 BROADWAY SUITE 2600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
441696	LOCATION	AC			-	Evans 7-26 Pad	RI

General Comment:[This is an Interim Reclamation and Stormwater Inspection.](#)

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: IRRIGATED

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____ Fail _____

Comment _____

Operator has stockpiles around both sets of wells along the northern location. Stockpiles have been temporarily stabilized with equipment tracking and an attempt to seed into the stockpiles is evident with drill rows and straw crimped mulch. However, there was little establishment of desirable species. Currently stockpiles have mostly Kochia establishment with no perennial vegetation that would compete with the weedy vegetation and generally work to decrease weed growth. Refer to the attached inspection photos.

Note: weed maintenance will need to be performed in the near future.

Corrective Action _____

Comply with Rule 1002.c. to protect all stockpiles from erosion and prevent weed establishment. If reseeding is a continued option for long-term protection and stabilization of stockpiles, reseeding shall be conducted no later than 11/16/2020 or as soon as environmental conditions will permit.

Date **11/16/2020**

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ In _____	Production areas stabilized ? _____
1003c. Compacted areas have been cross ripped? _____	
1003d. Drilling pit closed? _____	Subsidence over on drill pit? _____
Cuttings management: _____	
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____	
Production areas have been stabilized? _____	Segregated soils have been replaced? _____
RESTORATION AND REVEGETATION	
<u>Cropland</u>	
Top soil replaced _____	Recontoured _____
Perennial forage re-established _____	
<u>Non-Cropland</u>	
Top soil replaced _____	Recontoured _____
80% Revegetation _____	
1003e. INTERIM VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA% _____	
TRANSECT RESULTS OF REFERENCE AREA% _____	
TOTAL % OF DESIRABLE VEGETATION COVER _____	
VEGETATIVE COVER _____	
1003 f. Weeds Noxious weeds? _____	
Comment	Interim reclamation activities have been performed to reduce disturbance areas only needed for production operations. Vegetation throughout the interim areas (e.g., northern area) has not met Rule 1003 standards and will remain IN-PROCESS. Operator shall continue to monitor and manage this site until the location meets Rule 1003 standards, including stormwater and weed management. Operator shall submit a Form 4 Interim Reclamation Complete notice when the location meets Rule 1003 standards. COGCC may conduct inspections prior to receiving said notice to ensure compliance with Rule 1003.
Corrective Action	
Date	_____
Overall Interim Reclamation	In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____	Date Final Reclamation Completed: _____
Final Land Use: IRRIGATED _____	
Reminder: _____	
Comment: _____	
Well plugged _____	Pit mouse/rat holes, cellars backfilled _____
Debris removed _____	No disturbance /Location never built _____
Access Roads _____	Culverts removed _____
Regraded _____	Contoured _____
Gravel removed _____	
Location and associated production facilities reclaimed _____	Locations, facilities, roads, recontoured _____
Compaction alleviation _____	Dust and erosion control _____
Non cropland: Revegetated 80% _____	Cropland: perennial forage _____
Weeds present _____	Subsidence _____
1004.d. FINAL VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA% _____	
TRANSECT RESULTS OF REFERENCE AREA% _____	
TOTAL % OF DESIRABLE VEGETATION COVER _____	
VEGETATIVE COVER _____	

Comment:						
Corrective Action:						Date
Overall Final Reclamation		Well Release on Active Location <input type="checkbox"/>		Multi-Well Location <input type="checkbox"/>		

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:	<p>A culvert is in need of repair that directs stormwater to a stabilized outlet area.</p> <p>Retention areas with stabilized outlets areas were observed along the southern perimeter of location.</p> <p>Operator shall continue to monitor and manage this site for stormwater run on and runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.</p>					
Corrective Action:	Install or repair required BMPs per Rule 1002.f.					Date: 06/17/2020

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697501592	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5165220