

Inspection Photos

6/05/2020

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335275

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335275



Photo 1: Photo taken from the west end of the Location, facing west. Photo shows BMPs remain insufficient or missing; stormwater runoff has caused erosion degradation on the slopes, cutting into the hillside; Water appears to be undercutting large rocks; potential rockfall risk.



Photo 2: : Photo taken from the west end of the Location, facing southwest. See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335275



Photo 3: Photo shows additional armoring has been placed within ditch.



Photo 4: Photo taken from the east end of the Location, facing east. Photo shows erosion degradation on slopes; BMPs to stabilize and protect slopes remain insufficient or missing.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335275



Photo 5: See comments under photo 4.



Photo 6: Photo taken from the slopes on the east end of the Location, facing east. Photo shows Operator has installed straw bales to prevent sediment deposition off location.