

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402429183

Date Received:  
06/23/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100321  
Name of Operator: ROCKY MTN NATURAL GAS LLC ADBA BLACK HILLS ENERGY  
Address: 1515 ARAPAHOE ST TOWER 1  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Ally Little</u>	<u>307-778-2123</u>	<u>ally.little@blackhillscorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 692402253  
Inspection Date: 05/28/2020 FIR Submit Date: 06/08/2020 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: ROCKY MTN NATURAL GAS LLC ADBA BLACK HILLS ENERGY Company Number: 100321  
Address: 1515 ARAPAHOE ST TOWER 1  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 314170

Location Name: WOLF CREEK UNIT-68S90W Number: 35NWSE County: \_\_\_\_\_  
Qtrqtr: NWSE Sec: 35 Twp: 8S Range: 90W Meridian: 6  
Latitude: 39.314505 Longitude: -107.404633

FACILITY - API Number: 05-097-00 Facility ID: 314170

Facility Name: WOLF CREEK UNIT-68S90W Number: 35NWSE  
Qtrqtr: NWSE Sec: 35 Twp: 8S Range: 90W Meridian: 6  
Latitude: 39.314505 Longitude: -107.404633

CORRECTIVE ACTIIONS:

1 CA# 139561

Corrective Action: Install proper guy line markers per Rule 1003.a Date: 06/23/2020

Response: CA COMPLETED Date of Completion: 06/17/2020

Operator Comment: Guy line markers were removed from the site. They are no longer needed, so RMNG took them out.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

2 CA# 139562

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 07/08/2020

Response: CA COMPLETED

Date of Completion: 06/17/2020

Operator  
Comment:

The exposed line where soil compacted was buried with gravel from an existing stockpile.

The other inspection finding was in regard to the ditch onsite. The ditch is sloped toward a settling pond that allows sediment from water runoff to settle out before evaporating. The ditch was not altered and is functioning as designed.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Thanks for including pictures. If you would like more information about the settling pond in the corner of the site, please let me know. These settling ponds were created because of a request from USFS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ally Little

Signed: \_\_\_\_\_

Title: Environmental Professiona

Date: 6/23/2020 2:24:43 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

<b><u>Document Number</u></b>	<b><u>Description</u></b>

Total Attach: 0 Files