

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/26/2020

Submitted Date:

06/28/2020

Document Number:

688308081

**FIELD INSPECTION FORM**

Loc ID 317130 Inspector Name: Sherman, Susan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 31257  
Name of Operator: FRITZLER RESOURCES INC  
Address: P O BOX 114  
City: FORT MORGAN State: CO Zip: 80701

**Findings:**

- 13 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236633	WELL	PR	06/26/1990	OW	121-09124	WAGERS 11-4	PR

**General Comment:**

Reinspection, badger holes at sign fixed, tanks not labeled and animal holes in tank berms and pit berms, maintain vault berms

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	concrete vault and fiberglass tank need labels and maintenance (see attached photos)		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	08/08/2019

Emergency Contact Number:

Comment: 970-867-1268

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type PUMP JACK

Comment:

Corrective Action:

Date:

**Equipment:**

Type	#	Comment	Corrective Action	Date	corrective date
Type: Deadman # & Marked	# 4	dryland			
Type: Vertical Heater Treater	# 1	propane			
Type: Prime Mover	# 1	electric			
Type: Pump Jack	# 1				

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				Inadequate

Comment: [Maintain berms around vault.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#) Date: 07/08/2019

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	FIBERGLASS AST		,

Comment:

Corrective Action:

Date:

**Paint**

Condition

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			

Comment:

Corrective Action:

Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		,

Comment:

Corrective Action:

Date:

**Paint**

Condition

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				Inadequate

Comment: [Animal holes in berms.](#)

Corrective Action: [Maintain BMPs.](#) Date: 07/20/2020

**Venting:**

Yes/No NO

Comment:

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Location Construction**

Location ID: 236633 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** No COAs.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_ Date: \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Inspected Facilities**

Facility ID: 236633 Type: WELL API Number: 121-09124 Status: PR Insp. Status: PR

**Producing Well**

Comment: [PR. 2/1/2020 production reported to COGCC database.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: \_\_\_\_\_ Lat: \_\_\_\_\_ Long: \_\_\_\_\_

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: None Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: animal holes in pit berms

Corrective Action

Date: \_\_\_\_\_

Type: Produced Water Lined: NO Pit ID: \_\_\_\_\_ Lat: \_\_\_\_\_ Long: \_\_\_\_\_

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: None Fencing Condition: \_\_\_\_\_

Comment: dryland crop

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:		Date:
Corrective Action		
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:	<a href="#">Animal holes on south side of pit berms and west side of other pit.</a>	
Corrective Action	<b>Maintain pit berms on both pits.</b>	
		Date: <u>07/20/2020</u>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402433039	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5186099">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5186099</a>
688308084	Fritzler Resources WAgers 11-4	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5186095">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5186095</a>