

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402318737

Date Received:

02/20/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>
<u>Ray, Mandy</u>	<u>(505) 599-4083</u>	<u>mray@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901259

Inspection Date: 12/20/2019

FIR Submit Date: 12/23/2019

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 325480

Location Name: BURKETT-N34N8W Number: 3SWNE County: LA PLATA

Qtrqr: SWNE Sec: 3 Twp: 34N Range: 8W Meridian: N

Latitude: 37.246570 Longitude: -107.729080

FACILITY - API Number: 05-067- -00 Facility ID: 214860

Facility Name: BURKETT Number: 1-3

Qtrqr: SWNE Sec: 3 Twp: 34N Range: 8W Meridian: N

Latitude: 37.246570 Longitude: -107.729080

CORRECTIVE ACTIONS:

1 ☒ CA# 135570

Corrective Action: Revegetation/seeding needs to be conducted within the northwestern project area and spot seeding in any other areas with little desirable vegetation. Livestock exclusion may be needed for vegetation establishment.

Date: 04/01/2020

Response: CA COMPLETED

Date of Completion: 01/31/2020

Operator Comment: BP will reseed location due to work preformed on location in the spring time.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 135571

Corrective Action: Stormwater controls (ie BMPs) and erosion controls (ie mulching/erosion blankets) need to be installed along with seeding to stabilize erosion within the project area. Stormwater and erosion controls need to be selected, sized, and installed according to good engineering practices, and need to be maintained until location achieves stabilization with desirable perennial vegetation.

Date: 04/01/2020

Response: CA COMPLETED

Date of Completion: 01/31/2020

Operator Comment: BP had 2 hyro-vac trucks on location, since work on the cans is now completed they have back dragged the mud ruts from their trucks

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amanda Walker

Signed: _____

Title: Operation/Regulatory Tech

Date: 2/20/2020 2:55:06 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402318737	FIR RESOLUTION SUBMITTED
402318750	Followup Photos

Total Attach: 2 Files