

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402445157

Date Received:

07/16/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Murray, Richard

g.richard.murray@state.co.us

COGCCInspectionReports@terraep.com

mgardner@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 692402359

Inspection Date: 06/30/2020

FIR Submit Date: 07/07/2020

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 419862

Location Name: Mead Number: RWF 43-23 County: GARFIELD

Qtrqr: NESE Sec: 23 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.510016 Longitude: -107.846865

FACILITY - API Number: 05-045- -00 Facility ID: 419868

Facility Name: Mead Number: RWF 542-23

Qtrqr: NESE Sec: 23 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.510016 Longitude: -107.846865

CORRECTIVE ACTIONS:

1 CA# 140287

Corrective Action: Comply with Rule 603.f
For unused, unmarked flowline risers ; 24 hrs to lock out tag out (which has been
completed)and 30 days to remove risers (which has not been completed). CA DAta is
left at Date from previous unresolved CA.

Date: 06/23/2019

Response: CA COMPLETED

Date of Completion: 07/16/2020

The risers identified in this corrective action comply with Rule 1101.a.(1) A - D and do not require removal. TEP

Operator Comment: wishes to leave the risers in place in anticipation of drilling additional wells at this location if/ when economic conditions improve. The risers have been marked / tagged appropriately and are not considered to be "unused equipment."

COGCC Decision: _____

COGCC Representative: _____

2 CA# 140288

Corrective Action: Contact Western Integrity Inspector, Richard Murray to discuss Flowline/Risers CA given in Unused Equipment, above.

Date: 07/10/2020

Response: CA COMPLETED

Date of Completion: 07/16/2020

Operator Comment: TEP discussed this matter with Richard Murray on July 16, 2020. COGCC and TEP are in agreement that the lines meet the requirements of Rule 1101.a. (1) A-D, and as such, they do not require removal. An email outlining TEP's position was also sent to COGCC on July 14, 2020 and is attached to this FIRR.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Per conversation with Richard Murray (COGCC Western Region Integrity Inspector), the unused flowlines at this location are considered to be in Pre-Commissioned Status and as such comply with Rule 1101.a.(1)A-D. The risers have been appropriately tagged and locked out, and are not considered to be unused equipment. The risers/lines will remain in place to support future drilling at this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental

Date: 7/16/2020 3:23:11 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402445179	Correspondence dated July 14, 2020
-----------	------------------------------------

Total Attach: 1 Files