

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/03/2020

Submitted Date:

08/03/2020

Document Number:

693503260

FIELD INSPECTION FORMLoc ID 332971 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Lara-Mesa,	303-825-4822	cogcc@kpk.com	All inspections
		curtis.haverkamp@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239987	WELL	PR	02/01/2020	OW	123-07775	HLADKY-O'GORMAN 3	SI

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Access road blocked by irrigation pipe.		
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	<input style="width: 500px;" type="text"/>
Corrective Action:	<input style="width: 500px;" type="text"/> Date: <input style="width: 100px;" type="text"/>

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds in and around location and equipment on site.		
Corrective Action:	Comply with rule 603 f	Date:	08/10/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Barb wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Square tubing with hog fence		
Corrective Action:		Date:	

Equipment:				corrective date	
Type: Prime Mover	# 1				
Comment:	Electric motor				
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 1				
Comment:					
Corrective Action:				Date:	
Type: Pump Jack	# 1				
Comment:					
Corrective Action:				Date:	
Type: Gas Meter Run	# 2				
Comment:					
Corrective Action:				Date:	
Type: Bird Protectors	# 1				
Comment:					
Corrective Action:				Date:	
Type: Bradenhead	# 1				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:	Electric panel				
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	CONCRETE SUMP/VAULT		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)	50bbl				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:	Shares containment with crude oil tank					
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		,	
Comment:						

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment: Berm has been breached on west side do to farmer watering field.				
Corrective Action: Comply with rule 605 a 4 to repair berm till long term resolution is determined.				Date: <u>08/10/2020</u>

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	50bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shares containment with crude oil tank				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 239987 Type: WELL API Number: 123-07775 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDSComment: SI At time of inspection well is shut in.Corrective Action: Date: **COGCC Comments**

Comment

User

Date

COGCC Inspection Report Summary

On Monday Aug 3 2020 at approximately 12:45PM, I, Inspector Randy Silver, Conducted an on-site follow up inspection.

Location: Hladky O'Gorman #3

Operator: KP Kauffman

API#:05-123-07775

County: Weld

While there, I observed a shut in well head and production facility.

During this inspection the following possible compliance issues were observed:

Weeds: Rule 603f Corrective action date of 8-10-20 See photos 2,4,5,6,7,8,9,10,12

Berm: Rule 605 a 4 Corrective action date of 8-10-20 See photo 9

Weather conditions: Sunny and dry

This is a follow up inspection per doc#693501299 at time of inspection it appears all corrective actions have been addressed but new compliance issues have been observed. .

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

silverr

08/03/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693503261	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5215486