

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402458215

Date Received:

08/03/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 5 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Inspections, All

SanJuanCOGCC@bp.com

Fischer, Alex

alex.fischer@state.co.us

Beebe, Sabre

970-779-9398

Sabre.Beebe@bpx.com

Heil, John

john.heil@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 688800748

Inspection Date: 07/08/2020

FIR Submit Date: 07/08/2020

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: _____

Location Name: _____ Number: _____ County: _____

Qtrqr: SENW Sec: 16 Twp: 34N Range: 9W Meridian: M

Latitude: 37.194643 Longitude: -107.834841

FACILITY - API Number: 05-067- -00 Facility ID: 477145

Facility Name: Craig 1 Number: _____

Qtrqr: SENW Sec: 16 Twp: 34N Range: 9W Meridian: M

Latitude: 37.194643 Longitude: -107.834841

CORRECTIVE ACTIONS:

1 CA# 140328

Corrective Action: Secondary containment is inadequate to contain largest single tank plus sufficient freeboard.

Date: 08/07/2020

Response: CA COMPLETED

Date of Completion: 07/21/2020

Secondary containment berm constructed around tank

Operator
Comment:

COGCC Decision:

COGCC
Representative:

3 CA# 140330

Corrective Action: Comply with Rule 603.f.

Date: 07/22/2020

Response: CA COMPLETED

Date of Completion: 07/24/2020

Operator
Comment:

Location is designated by landowner as no spray pad. Weeds were cut down around equipment and on pad see attached.

COGCC Decision:

COGCC
Representative:

4 CA# 140331

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 08/07/2020

Response: CA COMPLETED

Date of Completion: 07/21/2020

Operator
Comment:

Please refer to document #402447891 for spill actions on control and containment of spill

COGCC Decision:

COGCC
Representative:

5 CA# 140332

Corrective Action: Submit a Form 27 Site Investigation and Remediation Workplan to close pit. Contact COGCC EPS staff.

Date: 07/17/2020

Response: CA COMPLETED

Date of Completion: 07/20/2020

Operator
Comment:

After days of searching all records on this well BPX has no documentation or knowledge in regards to pits on location. BPX is 3rd owner of well pad and has no documentation regarding said pit and/or closure of said pit. This pit most likely was a drill pit utilized by first owner and was closed after drilling and completion of the well. However, BPX can neither confirm nor deny this pit ever existed.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All CA addressed except tank sign which is on order and will be closed out with another FIRR form.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed:

Title: Specialist

Date: 8/3/2020 1:13:03 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402458235	Weed mowing photos

Total Attach: 1 Files