

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/03/2020

Submitted Date:

08/04/2020

Document Number:

690200494

FIELD INSPECTION FORM

Loc ID 307317 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD State: CO Zip: 8111-

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fitzgerald, Edie		ediefitzgerald@tcenergyllc.com	
Mack, Ronald		ronaldmack@tcenergyllc.com	
BAKER DAVID		dbaker@auroramp.com	
Dylan Thomsen		timothy.thomsen@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217446	WELL	PR	10/01/1996	GW	071-06223	APACHE CANYON 20-1	RI

General Comment:

[This is a stormwater management inspection.](#)
[See attached photos and additional details within this report.](#)

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Fail			

Comment: There has been significant recent precipitation events that caused erosion along the main road. There are multiple culverts that have filled in with sediment which must be cleaned out and maintained. The next storm event could cause additional erosion and degradation of the road if BMP's aren't maintained. Maintaining BMP's will reduce erosion and additional issues. There was a backhoe operating along the road pushing mud and debris so maintenance appears to be under way. Ongoing maintenance needs to occur field wide.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 08/25/2020

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690200495	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5216463