

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402347605

Date Received:

03/23/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Sabre Beebe 970-779-9398 SanJuanCOGCC@bp.com

Sabre Beebe 970-779-9398 sabre.beebe@bpx.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680603286

Inspection Date: 10/30/2018

FIR Submit Date: 11/08/2018

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 325595

Location Name: BONDS GAS UNIT-N32N10W Number: 1SWSE County: LA PLATA

Qtrqtr: SWSE Sec: 1 Twp: 32N Range: 10W Meridian: N

Latitude: 37.041568 Longitude: -107.882923

FACILITY - API Number: 05-067- -00 Facility ID: 215062

Facility Name: BONDS Number: 3E

Qtrqtr: SWSE Sec: 1 Twp: 32N Range: 10W Meridian: N

Latitude: 37.041568 Longitude: -107.882923

CORRECTIVE ACTIONS:

1 ☒ CA# 120304

Corrective Action: Remove equipment and reclaim project area, including recontouring, decompaction, and revegetation within the spring planting window and no later than April 30, 2019. Weeds need to be controlled at the appropriate time but no later than June 15, 2019.

Date: 04/30/2019

Response: CA COMPLETED

Date of Completion: 03/12/2020

Operator Comment: Red Cedar removed their equipment that was remaining on location with the exception of the active cathodic rectifier which remains in service for the active pipeline corrosion protection. Preemergent weed treatment performed with herbicide. A week later seeding of bare and recently disturbed areas performed all slopes were covered with biodegradable matting to protect the seed and slow down stormwater flows. A stormwater basin

was installed with armored matting on the NE corner of the pad where erosion was beginning to occur. Landowner removed their agricultural production equipment from location.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 120305

Corrective Action: Stabilize erosion within the project area. Reclamation and revegetation of the well pad will help stabilization. Stormwater controls and erosion controls will be needed until location meets final revegetation standards.

Date: 12/14/2018

Response: CA COMPLETED

Date of Completion: 03/12/2020

Operator Comment: Red Cedar removed their equipment that was remaining on location with the exception of the active cathodic rectifier which remains in service for the active pipeline corrosion protection. Preemergent weed treatment performed with herbicide. A week later seeding of bare and recently disturbed areas performed all slopes were covered with biodegradable matting to protect the seed and slow down stormwater flows. A stormwater basin was installed with armored matting on the NE corner of the pad where erosion was beginning to occur. Landowner removed their agricultural production equipment from location.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: stormwater, weeds and equipment has been addressed on location. Variance being worked with enforcement group.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Specialist

Date: 3/23/2020 11:33:10 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402347605	FIR RESOLUTION SUBMITTED
402347639	Photos

Total Attach: 2 Files