

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402374366

Date Received:

04/17/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Tamra Sessions

505-324-4145

tsessions@logosresourcesllc.com

Marie Florez

505-787-2218

mflorez@logosresourcesllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901463

Inspection Date: 02/27/2020

FIR Submit Date: 03/02/2020

FIR Status: _____

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

LOCATION - Location ID: 306954

Location Name: BONDAD 33-9-N33N9W Number: 31NWSW County: LA PLATA

Qtrqr: NWS Sec: 31 Twp: 33N Range: 9W Meridian: N
W

Latitude: 37.058290 Longitude: -107.874530

FACILITY - API Number: 05-067- -00 Facility ID: 284286

Facility Name: BONDAD 33-9 Number: 54

Qtrqr: NWS Sec: 31 Twp: 33N Range: 9W Meridian: N
W

Latitude: 37.058290 Longitude: -107.874530

CORRECTIVE ACTIONS:

1 ☒ CA# 136824

Corrective Action: Revegetation needs to be conducted in areas where vegetation is sparse, bare, and/or killed. Soil testing and amendment/remediation may be needed for successful revegetation.

Date: 05/01/2020

Response: CA COMPLETED

Date of Completion: 04/13/2020

The vegetation mentioned in document# 693901463 along the pipeline right of way, near the well pad entrance is below the fill slope and out of LOGOS Operating LLC's project area. LOGOS has contacted Harvest

Operator Comment: midstream about the killed vegetation, because the dead vegetation is outside of LOGOS's project area, we are not authorized to impact the area over Harvest's pipeline on private property. We have worked with Harvest midstream to ensure awareness of the dead vegetation and will continue to encourage them to revegetate in areas where vegetation is sparse, bare, and/or killed outside of LOGOS's project area.

COGCC Decision: **Not Approved**

COGCC Representative: Operator response does not demonstrate that corrective action is addressed.

OPERATOR COMMENT AND SUBMITTAL

Comment: The vegetation mentioned in document# 693901463 along the pipeline right of way, near the well pad entrance is below the fill slope and out of LOGOS Operating LLC's project area. LOGOS has contacted Harvest midstream about the killed vegetation, because the dead vegetation is outside of LOGOS's project area, we are not authorized to impact the area over Harvest's pipeline on private property. We have worked with Harvest midstream to ensure awareness of the dead vegetation and will continue to encourage them to revegetate in areas where vegetation is sparse, bare, and/or killed outside of LOGOS's project area.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tamra Sessions

Signed: _____

Title: Regulatory Specialist

Date: 4/17/2020 2:38:02 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402374366	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files