

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402387690

Date Received:
05/01/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Shorty, Priscilla

pshorty@hilcorp.com

Ray, Mandy

(505) 599-4083

mray@hilcorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901604

Inspection Date: 04/03/2020

FIR Submit Date: 04/06/2020

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 333865

Location Name: PACHECO 32-7-N32N7W Number: 12SESW County: LA PLATA

Qtrqtr: SESW Sec: 12 Twp: 32N Range: 7W Meridian: N

Latitude: 37.027760 Longitude: -107.563690

FACILITY - API Number: 05-067- -00 Facility ID: 263202

Facility Name: PACHECO 32-7 Number: 12-3

Qtrqtr: SESW Sec: 12 Twp: 32N Range: 7W Meridian: N

Latitude: 37.027760 Longitude: -107.563690

CORRECTIVE ACTIONS:

1 ☒ CA# 137730

Corrective Action: Remove and properly dispose of weed debris.

Date: 04/20/2020

Response: CA COMPLETED

Date of Completion: 04/29/2020

Operator Comment: Weed debris were removed. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 137731

Corrective Action: Revegetation needs to be conducted within the majority of the interim reclamation areas, where little desirable vegetation is present.

Date: 05/01/2020

Response: CA COMPLETED

Date of Completion: 04/29/2020

Operator
Comment: Revegetation was conducted. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 137732

Corrective Action: -Erosion controls (such as mulch) and stormwater controls (such as BMPs) are needed within the project area until interim reclamation areas are stabilized with desirable perennial vegetation.

Date: 05/01/2020

Response: CA COMPLETED

Date of Completion: 04/29/2020

Operator
Comment: Erosion controls were implemented within project area. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed:

Title: OperationsRegulatory Tech

Date: 5/1/2020 1:53:21 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402387690	FIR RESOLUTION SUBMITTED
402387712	PACHECO 32-7 12-3_Resolved Photos

Total Attach: 2 Files