

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402392717

Date Received:
05/07/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>
<u>Ray, Mandy</u>	<u>(505) 599-4083</u>	<u>mray@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693901214
Inspection Date: 12/13/2019 FIR Submit Date: 12/17/2019 FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 325300

Location Name: SQUIRES-N32N7W Number: 1NENE County: LA PLATA
Qtrqr: NENE Sec: 1 Twp: 32N Range: 7W Meridian: N
Latitude: 37.051110 Longitude: -107.554590

FACILITY - API Number: 05-067- -00 Facility ID: 214515

Facility Name: SQUIRES Number: 1
Qtrqr: NENE Sec: 1 Twp: 32N Range: 7W Meridian: N
Latitude: 37.051110 Longitude: -107.554590

CORRECTIVE ACTIONS:

1 ☒ CA# 135394

Corrective Action: Revegetation needs to be installed by 4/1/2020. Weeds need to be controlled at the appropriate time but no later than 5/1/2020. Please note that herbicide application on young seedlings will likely adversely effect seedling establishment. Livestock exclusion appears needed for successful revegetation.

Date: 05/01/2020

Response: CA COMPLETED Date of Completion: 05/04/2020

Operator Comment: Weeds removed. Re-contouring and control ditches installed. Revegetation with mulch is completed. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 135395

Corrective Action: Stormwater controls (ie BMPs) need to be installed immediately to stabilize erosion within the project area. Erosion controls (ie mulching and erosion blankets) need to be installed at the time of seeding and no later than 4/1/2020. Stormwater erosion is documented on multiple inspections since 2015. Corective action is backdated to document duration of non-compliance since previous inspection.

Date: 10/10/2018

Response: CA COMPLETED

Date of Completion: 05/04/2020

Operator Comment: Weeds removed. Re-contouring and control ditches installed. Revegetation with mulch is completed. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: _____

Title: OperationsRegulatory Tech

Date: 5/7/2020 2:06:59 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402392717	FIR RESOLUTION SUBMITTED
-----------	--------------------------

402392729	Squires 1_Resolved Photos
-----------	---------------------------

Total Attach: 2 Files